

## LENTOKELPOISUUSMÄÄRÄYKSET

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
<b>LENTOKONEET - L</b>				
<b>Airbus</b>				
<b>A319-112</b>				
EASA2006-0135	5.6.2006	AFMTR2.05.00/67	Speed limitation when Ram Air Turbine deploy	jp
EASA2006-0136	5.6.2006	A320-54A1015R2	Engine Pylon Spar Box Ribs	jp
EASA2006-0153	R2 26.6.2006	A320-49-1068R1	APU starter motor and air intake system inspe	Read AD
EASA2006-0236	R1 9.3.2007	Read AD	Fuel system - Labels in Fuel Tank	Read AD
EASA2007-0036	R1 16.2.2007	A320-71A1042R1	Forward Engine Mount Bolts - Inspection/Repl	Read AD
EASA2007-0064	R1 5.10.2007	SB A320-57-1121	Dry bay skin inspection	27.11.2008
EASA2007-0065	R2 14.3.2011	Read AD	Extension and retraction selector valves inspe	Read AD
EASA2007-0067	R1 27.3.2007	Read AD	Center and outer wing box at level of rb 1 junct	Read AD
EASA2007-0161	25.6.2007	A320-53-1195/6	Inspection MLG door keel beam hinge & actua	X
EASA2007-0163	25.6.2007	A320-27-1132R1	Inspection of elevator backlash	20KK
EASA2007-0214	21.8.2007	A320-25-1535	103VU box hinge pin stopper modification	31.3.2009
EASA2007-0217	23.8.2007	Read AD	Northrop-Grumman ADIRU replacement	Read AD
EASA2007-0218	R1 14.3.2011	SB A320-28-1159	Fuel pumps airworthiness limitations / inspecti	7.9.2007
EASA2007-0249	8.10.2007	SB A320-26A1068	Inspection of fire extinguishing circuit system	600 FH
EASA2007-0276	R1 18.3.2010	Read AD	80VU rack attachments inspection / repair / r	Read AD
EASA2007-0286	28.11.2007	SB A320-33-1057	Emergency lighting for stand-by instruments m	27.11.2011
EASA2008-0032	6.3.2008	Read AD	EIS2 standard S7 installation	Read AD
EASA2008-0048	13.3.2008		Braking and steering control unit modification	X
EASA2008-0150	19.8.2008	A320-27-1164R6	Trimmable horizontal stabilizer actuator	10KK/20KK
EASA2008-0151	19.8.2008	A320-25-1444	Cockpit door latch/striker assembly	31032009
EASA2008-0191-E	21.10.2008	AOT A320-71A1045	Rear engine mount barrel nuts inspection	28.10.2008
EASA2008-0198	18.11.2008	SB A320-31-1286	EIS DMC software update	30.11.2013
EASA2009-0025	24.2.2009	Read AD	Flap track no.1 pendulum assembly inspection	600FH
EASA2009-0141	16.7.2009	AOT A320-55A1038	Inspection of rudder side shell skin	SEE AD
EASA2009-0235	12.11.2009	A320-24-1120R3	Modification of AC and DC ESS power supply	12112013
EASA2009-0252	10.12.2009	Read AD	Door modification	Read AD
EASA2010-0046	2.4.2010	Read AD	Elevator servo-control rod eye-end inspection	Read AD
EASA2010-0071	R1 11.6.2010	Read AD	Damage tolerant airworthiness limitation items	Read AD
EASA2010-0071	29.4.2010	See AD	Damage tolrant airworthiness limitations	SEE AD
EASA2010-0091	R1 26.10.2010	A320-55A1040	Elevators inspection	Read AD
EASA2010-0120	5.7.2010	AOT A320-29A1150	Hamilton Sundstrand ram air turbine balance w	Read AD
EASA2010-0148	4.8.2010	Read AD	DASELL lavatory walls inspection/repair	26.6.2006
EASA2010-0164	19.8.2010	Read AD	Rudder side shell skin inspection	1.2.2010
EASA2010-0177	13.9.2010	A320-28-1162r01	Additional centre tanks manhole cover seal rep	Read AD
EASA2010-0209	28.10.2010	A320-57-1133R5	Inboard flap trunnion and sliding panel inspecti	SEE AD

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2010-0210		22.10.2010	A320-25-1649	Off-wing escape slide enclosure	4.11.2013
EASA2011-0001		24.1.2011	A320-31-1334R2	Replacement of flight warning computers	X
EASA2011-0011		4.2.2011	A320-57A1166	MLG support rib 5 fitting	SEE AD
EASA2011-0015		14.2.2011	See AD	Replacement of escape slide release cables	14022014
EASA2011-0024	R1	14.3.2011	Read AD	MLG side-stay cuff lug inspection / repair	Read AD
EASA2011-0034		16.3.2011	A320-57-1152	Outer wing refuelling aperture electrical bondin	16.3.2013
EASA2011-0054		7.4.2011	A320-92A1072	Replacement of terminal modules in electronic	X
EASA2011-0069		2.5.2011		Main landing gear door actuator - monitoring/in	Read AD
EASA2011-0077		19.5.2011	A320-25-1294 r6	Cargo loading system fixed YZ latches attache	19.1.2013
EASA2011-0120	R1	27.7.2011	A320-53-1218	Nuts Inspection/Replacement	Read AD
EASA2011-0121	R1	27.7.2011	A320-57-1153	Nuts Inspection / Replacement	Read AD
EASA2011-0134		29.7.2011	A320-53-1060R2	Inspection of keel beam side panels	Read AD
EASA2011-0137		4.8.2011	A320-25A1757	PAX compartment class divider gas spring da	04112011
EASA2011-0142		25.7.2011	AFM TR112	Display unit failure operational procedure	18.8.2011
EASA2011-0155		8.9.2011	ALS Part 5	Fuel airworthiness limitations	X
EASA2011-0160		9.9.2011	A320-25-1723/4	Replacement of escape slide raft	09092014
EASA2011-0167		20.9.2011	A320-35A1047	Modification of chemical emergency oxygen co	20052013
EASA2011-0201		27.10.2011	Read AD	Inspection of NLG braking & steering control u	Read AD
EASA2011-0202		27.10.2011	Read AD	Landing gear control and interface unit wiring -	Read AD
EASA-2011-0203		27.10.2011	SB A320-34-1452	Replacement of angle of attack probes	27102012
EASA2011-0203		27.10.2011	SB A320-34-1452	Angle of attack (AoA) probes - replacement	27.10.2012
EASA2011-0231		23.12.2011	A320-53-1245R1	Winshield central lower node continuity fitting	X
F-1996-271-092	R3	11.8.1999	A320-27-1108R3	Inboard flap trunnion	X
F-1997-203-102	R1	8.4.1998	A320-30-1036	Probe heat computer	X
F-1998-178-115		6.5.1998	A320-25-1186	Improvement of avionic protection	X
F-1998-341	R1	23.9.1998	A320-25-1208	Sicma aero seats	X
F-1998-451-121		18.11.1998	A320-34-1163	ILS receiver	X
F-1998-482-122	R1	21.4.1999	A320-52-1094R1	Passenger & emergency door act.	X
F-1999-124-129		24.3.1999	A320-32-1197	Nose landing gear wheel rotation	X
F-1999-361-138		8.9.1999	A320-34-1191/6	Litton GPSSU	X
F-1999-362-139		18.9.1999	A320-27-1126/7	Spoiler servocontrols	30101999
F-1999-411-140	R1	3.5.2000	A320-22-1063	FMGC new calculator	X
F-1999-412-141		20.10.1999	A320-29-1088	RAT actuator	X
F-2000-004-142		12.1.2000	A320-34-1030/1	Rockwell Collins radio altimeter	X
F-2000-256-145		14.6.2000	A320-25-120	Sliding footrest improvement	X
F-2000-258-146		14.6.2000	A320-32-1199/0	BDDV check & modification	X
F-2000-359-152	R2	23.2.2001	A320-25-1215	Emergency escape slides	X
F-2000-372-151		6.9.2000	A320-27-1042	Stiff rudder pedal	X
F-2000-428-153	R1	29.11.2000	A320-32-1119	Main landing gear pintle pin cross bolt	X
F-2000-518-157		13.12.2000	A320-56-1007	Cockpit sliding window mechanism	X

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
F-2000-519-158	13.12.2000	AOT52A1106	Passenger door outer handle	X
F-2000-520-159	13.12.2000	A320-55A1027R1	Vertical stabilizer spar box	X
F-2000-524	27.12.2000	TAA12-25-402R1	SOGERMA flight crew seats	X
F-2001-063	21.2.2001	A320-52-1102R1	PAX door slide raft girt bar	X
F-2001-100	21.3.2001	A320-52-1057	PAX door upper safety pin	X
F-2001-237	R1 25.7.2001	A320-35-1003/.16	Crew oxygen supply	31102002
F-2001-271	27.6.2001	A320-28A1096	Center tank fuel qt. Ind.	X
F-2001-362	8.8.2001	A320-34-1127	Pitot probes	08082003
F-2001-363	8.8.2001	A320-35-1022	Oxygen passenger containers	X
F-2001-380	5.9.2001	A320-25-1156R1	Offwing escape slide mod.	05092004
F-2001-384	R1 20.3.2002	ASB320-32A1233	Yellow hydraulic circuit - PBOV	(ASB)/3112
F-2001-508	17.10.2001	A320-27-1135	ELAC computer	31122002
F-2001-606	12.12.2001	A320-56A1010R1	PPG Aerospace windshields	30062002
F-2001-632	26.12.2001	A320-56-1009	Cockpit windows outer ply separation	(500H)
F-2001-634	26.12.2001	A320-53-1154	Rear PAX door frame upper guide rod fitting	31102003
F-2002-202	17.4.2002	A320-28-1077R4	Electrical bonding in fuel tanks	31122004
F-2002-220(B)	R1 15.10.2003	A320-28-1086/7	Modification of fuel probes	31122004
F-2002-221	30.4.2002	A320-28-1093	Wing fuel tanks pump wiring short-circuit	30042004
F-2002-337	R1 24.7.2002	Rohr RA32078-112	Thrust reverse piston rod chrome plating	X
F-2002-340	26.6.2002	A320-57-1051R4	Inspection of junction fuselage/wing fittings	X
F-2002-365	26.6.2002	A320-24-1092R4	Test after relay 11QG relocation	X
F-2002-453	R1 11.6.2003	A320-49-1057	APU APS 3200 exhaust tailpipe II	30062003
F-2002-456	R1 28.5.2003	A320-49-1057	APU APIC APS 3200 exhaust tailpipe	30062003
F-2002-458(B)	R2 29.10.2002	A320-34A1262R1	Thales Avionics DDRMI failure	09112002
F-2002-476	R1 21.1.2004	A320-28-1103R1	Additional electrical bonding in fuel tanks	31122007
F-2002-514	R1 13.11.2002	AMM27-34-00-200-	Elevator vibrations	31032003/1
F-2002-554	13.11.2002	A320-24-1099	Replacement of transformer rectifier unit	31032004
F-2002-586	R1 12.4.2003	A320-34-1263	Thales avionics pitot probes	X
F-2003-119	29.3.2003		Fuel leak procedure	29032003
F-2003-147	R1 16.4.2003	SB320-53-1147R2	Overwing emergency exit door frame corners	(3500 J)
F-2003-270	23.7.2003	-34-1231/1249/	Navigation - inertial reference systems	23072003
F-2003-434	10.12.2003	A320-52A§1086/96	MLG door actuator fitting	X
F-2004-019	4.2.2004	A320-24-1106	Hamilton Sundstrand APU generator	30102005
F-2004-032	18.2.2004	MPDSection 9-1R6	Life limits/monitored parts - MPD Section 9-1	X
F-2004-072	26.5.2040	A320-25-1338	PAX door emergency escape slides	30062007
F-2004-073	26.5.2004	A320-92-1032	Fuel - prevention against explosion risk	31122005
F-2004-120	31.7.2004	A320-28-1123	Fuel system air release valve	30062007
F-2004-121	R1 23.10.2004	A320-33-1041	Emergency escape path marking	31122005
F-2004-122	31.7.2004	A320-27-1158/9	Spoiler actuators	31072005
F-2004-123	R1 2.7.2005	A320-21-1141	Cargo compartment heating temp. sensor	31052007

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
F-2004-129	14.8.2004	A320-92-1007R8	Cable segregation around rack 90 VU	05082005
F-2004-137	20.11.2004	A320-32-1201R1	Parking brake system	31032009
F-2004-168	R1 20.10.2004	A320-34-1335	Loss of integrated standby instrument system	23102004
F-2004-172	R1 23.4.2005	A320-52-1124	Cargo compartment water drain valves	31122005
F-2004-189	R1 5.1.2005	A320-53A1158	MLG door actuator fitting	X
F-2005-040	12.3.2005	AMM25-28-12/42	Non-textile floor (NTF) replacement	31122009
F-2005-057	23.4.2005	A320-52-1112	PAX door slide raft telescopic girt bar	31122006
F-2005-101	2.7.2005	CMR	Certified limitations - MPD section 9-3	X
F-2005-108	16.6.2005	A320-28-1138	Fuel system - Magnetic fuel level indicator (MF	31122010
F-2005-115	16.6.2005	A320-32A1273 R2	Main landing gear (MLG)	AD
F-2005-164	8.10.2005	TAAI1-25-617	Cockpit seats actuators inspection	31052010
F-2005-165	8.10.2005		Fuel leak procedure	08102005
F-2005-172	31.12.2005	A320-25-1394R1	Forward passenger doors - Escape slide raft	X
F-2005-173	5.11.2005	A320-28-1059R6	Fuel system - Prevention against explosion ris	X
F-2005-189	3.12.2005	A320-28-1122	Fuel system - Twin motor low pressure valve a	X
F-2005-212	31.12.2005	A320-29-1124	Ram air turbine carbon blade	X
<b>A320-214</b>				
EASA2006-0135	5.6.2006	AFMTR2.05.00/67	Speed limitation when Ram Air Turbine deploy	jp
EASA2006-0136	5.6.2006	A320-54A1015R2	Engine Pylon Spar Box Ribs	jp
EASA2006-0153	R2 26.6.2006	A320-49-1068R1	APU starter motor and air intake system inspe	Read AD
EASA2006-0236	R1 9.3.2007	Read AD	Fuel system - Labels in Fuel Tank	Read AD
EASA2006-0262	8.9.2006	A320-55-1030	Replacement of rudder actuator fittings	X
EASA2007-0036	R1 16.2.2007	A320-71A1042R1	Forward Engine Mount Bolts - Inspection/Repl	Read AD
EASA2007-0064	R1 5.10.2007	SB A320-57-1121	Dry bay skin inspection	27.11.2008
EASA2007-0065	R2 14.3.2011	Read AD	Extension and retraction selector valves inspe	Read AD
EASA2007-0067	R1 27.3.2007	Read AD	Center and outer wing box at level of rb 1 junct	Read AD
EASA2007-0161	25.6.2007	A320-53-1195/6	Inspection MLG door keel beam hinge & actua	X
EASA2007-0163	25.6.2007	A320-27-1132R1	Inspection of elevator backlash	20KK
EASA2007-0214	21.8.2007	A320-25-1535	103VU box hinge pin stopper modification	31.3.2009
EASA2007-0217	23.8.2007	Read AD	Northrop-Grumman ADIRU replacement	Read AD
EASA2007-0218	R1 14.3.2011	SB A320-28-1159	Fuel pumps airworthiness limitations / inspecti	7.9.2007
EASA2007-0249	8.10.2007	SB A320-26A1068	Inspection of fire extinguishing circuit system	600 FH
EASA2007-0276	R1 18.3.2010	Read AD	80VU rack attachments inspection / repair / r	Read AD
EASA2007-0286	28.11.2007	SB A320-33-1057	Emergency lighting for stand-by instruments m	27.11.2011
EASA2008-0032	6.3.2008	Read AD	EIS2 standard S7 installation	Read AD
EASA2008-0034	R1 1.6.2010	A320-29-1122	Ram air turbine (RAT) gerotor pump replacem	31.5.2009
EASA2008-0048	13.3.2008		Braking and steering control unit modification	X
EASA2008-0051	R1 28.4.2010	A320-24-1062 R6	Prevention of fuel explosion risks electrical cab	Read AD
EASA2008-0150	19.8.2008	A320-27-1164R6	Trimmable horizontal stabilizer actuator	10KK/20KK
EASA2008-0151	19.8.2008	A320-25-1444	Cockpit door latch/striker assembly	31032009

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2008-0191-E		21.10.2008	AOT A320-71A1045	Rear engine mount barrel nuts inspection	28.10.2008
EASA2008-0198		18.11.2008	SB A320-31-1286	EIS DMC software update	30.11.2013
EASA2008-0199	R1	5.7.2010	A320-29-1136	Ram air turbine (RAT) ejection jack replaceme	19.11.2009
EASA2009-0025		24.2.2009	Read AD	Flap track no.1 pendulum assembly inspection	600FH
EASA2009-0141		16.7.2009	AOT A320-55A1038	Inspection of rudder side shell skin	SEE AD
EASA2009-0235		12.11.2009	A320-24-1120R3	Modification of AC and DC ESS power supply	12112013
EASA2009-0252		10.12.2009	Read AD	Door modification	Read AD
EASA2010-0046		2.4.2010	Read AD	Elevator servo-control rod eye-end inspection	Read AD
EASA2010-0071		29.4.2010	See AD	Damage tolrant airworthiness limitations	SEE AD
EASA2010-0071	R1	11.6.2010	Read AD	Damage tolerant airworthiness limitation items	Read AD
EASA2010-0091	R1	26.10.2010	A320-55A1040	Elevators inspection	Read AD
EASA2010-0120		5.7.2010	AOT A320-29A1150	Hamilton Sundstrand ram air turbine balance w	Read AD
EASA2010-0148		4.8.2010	Read AD	DASELL lavatory walls inspection/repair	26.6.2006
EASA2010-0149		4.8.2010	A320-27-1199 r1	Elevator aileron computer (ELAC) system pow	4.8.2012
EASA2010-0164		19.8.2010	Read AD	Rudder side shell skin inspection	1.2.2010
EASA2010-0177		13.9.2010	A320-28-1162r01	Additional centre tanks manhole cover seal rep	Read AD
EASA2010-0209		28.10.2010	A320-57-1133R5	Inboard flap trunnion and sliding panel inspecti	SEE AD
EASA2010-0210		22.10.2010	A320-25-1649	Off-wing escape slide enclosure	4.11.2013
EASA2011-0001		24.1.2011	A320-31-1334R2	Replacement of flight warning computers	X
EASA2011-0011		4.2.2011	A320-57A1166	MLG support rib 5 fitting	SEE AD
EASA2011-0015		14.2.2011	See AD	Replacement of escape slide release cables	14022014
EASA2011-0024	R1	14.3.2011	Read AD	MLG side-stay cuff lug inspection / repair	Read AD
EASA2011-0034		16.3.2011	A320-57-1152	Outer wing refuelling aperture electrical bondin	16.3.2013
EASA2011-0054		7.4.2011	A320-92A1072	Replacement of terminal modules in electronic	X
EASA2011-0069		2.5.2011		Main landing gear door actuator - monitoring/in	Read AD
EASA2011-0077		19.5.2011	A320-25-1294 r6	Cargo loading system fixed YZ latches attache	19.1.2013
EASA2011-0120	R1	27.7.2011	A320-53-1218	Nuts Inspection/Replacement	Read AD
EASA2011-0121	R1	27.7.2011	A320-57-1153	Nuts Inspection / Replacement	Read AD
EASA2011-0134		29.7.2011	A320-53-1060R2	Inspection of keel beam side panels	Read AD
EASA2011-0137		4.8.2011	A320-25A1757	PAX compartment class divider gas spring da	04112011
EASA2011-0142		25.7.2011	AFM TR112	Display unit failure operational procedure	18.8.2011
EASA2011-0155		8.9.2011	ALS Part 5	Fuel airworthiness limitations	X
EASA2011-0160		9.9.2011	A320-25-1723/4	Replacement of escape slide raft	09092014
EASA2011-0167		20.9.2011	A320-35A1047	Modification of chemical emergency oxygen co	20052013
EASA2011-0201		27.10.2011	Read AD	Inspection of NLG braking & steering control u	Read AD
EASA2011-0202		27.10.2011	Read AD	Landing gear control and interface unit wiring -	Read AD
EASA-2011-0203		27.10.2011	SB A320-34-1452	Replacement of angle of attack probes	27102012
EASA2011-0203		27.10.2011	SB A320-34-1452	Angle of attack (AoA) probes - replacement	27.10.2012
EASA2011-0229		20.12.2011	A320-53-1247	Forward fuselage frame (FR) 24 - inspection/m	24000 FCS
EASA2011-0231		23.12.2011	A320-53-1245R1	Winshield central lower node continuity fitting	X

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
F-1996-234-087	R1	30.10.2002	A320-53-1071	Door frame FR66	X
F-1996-271-092	R3	11.8.1999	A320-27-1108R3	Inboard flap trunnion	X
F-1997-203-102	R1	8.4.1998	A320-30-1036	Probe heat computer	X
F-1998-178-115		6.5.1998	A320-25-1186	Improvement of avionic protection	X
F-1998-341	R1	23.9.1998	A320-25-1208	Sicma aero seats	X
F-1998-451-121		18.11.1998	A320-34-1163	ILS receiver	X
F-1998-482-122	R1	21.4.1999	A320-52-1094R1	Passenger & emergency door act.	X
F-1999-124-129		24.3.1999	A320-32-1197	Nose landing gear wheel rotation	X
F-1999-148-130		7.4.1999	A320-52-1057R6	Passenger door safety pin greasing	X
F-1999-361-138		8.9.1999	A320-34-1191/6	Litton GPSSU	X
F-1999-362-139		18.9.1999	A320-27-1126/7	Spoiler servocontrols	30101999
F-1999-411-140	R1	3.5.2000	A320-22-1063	FMGC new calculator	X
F-1999-412-141		20.10.1999	A320-29-1088	RAT actuator	X
F-2000-004-142		12.1.2000	A320-34-1030/1	Rockwell Collins radio altimeter	X
F-2000-256-145		14.6.2000	A320-25-120	Sliding footrest improvement	X
F-2000-258-146		14.6.2000	A320-32-1199/0	BDDV check & modification	X
F-2000-359-152	R2	23.2.2001	A320-25-1215	Emergency escape slides	X
F-2000-372-151		6.9.2000	A320-27-1042	Stiff rudder pedal	X
F-2000-428-153	R1	29.11.2000	A320-32-1119	Main landing gear pintle pin cross bolt	X
F-2000-518-157		13.12.2000	A320-56-1007	Cockpit sliding window mechanism	X
F-2000-519-158		13.12.2000	AOT52A1106	Passenger door outer handle	X
F-2000-520-159		13.12.2000	A320-55A1027R1	Vertical stabilizer spar box	X
F-2000-524		27.12.2000	TAA12-25-402R1	SOGERMA flight crew seats	X
F-2000-531-155		27.12.2000	A320-53-1029/30	Fuselage frame 36	X
F-2001-062		21.2.2001	A320-55-1024	Reprotection of the elevator against water	X
F-2001-063		21.2.2001	A320-52-1102R1	PAX door slide raft girt bar	X
F-2001-100		21.3.2001	A320-52-1057	PAX door upper safety pin	X
F-2001-237	R1	25.7.2001	A320-35-1003/16	Crew oxygen supply	31102002
F-2001-249		27.6.2001	A320-57-1004	Wing rear spar inspection	(3600L/670
F-2001-271		27.6.2001	A320-28A1096	Center tank fuel qt. Ind.	X
F-2001-362		8.8.2001	A320-34-1127	Pitot probes	08082003
F-2001-363		8.8.2001	A320-35-1022	Oxygen passenger containers	X
F-2001-380		5.9.2001	A320-25-1156R1	Offwing escape slide mod.	05092004
F-2001-384	R1	20.3.2002	ASB320-32A1233	Yellow hydraulic circuit - PBOV	(ASB)/3112
F-2001-508		17.10.2001	A320-27-1135	ELAC computer	31122002
F-2001-606		12.12.2001	A320-56A1010R1	PPG Aerospace windshields	30062002
F-2001-632		26.12.2001	A320-56-1009	Cockpit windows outer ply separation	(500H)
F-2001-634		26.12.2001	A320-53-1154	Rear PAX door frame upper guide rod fitting	31102003
F-2002-183		3.4.2002	A320-53-1027/8	Pick-up angle between frame 35 & 36	(10400H)
F-2002-202		17.4.2002	A320-28-1077R4	Electrical bonding in fuel tanks	31122004

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
F-2002-220(B)	R1	15.10.2003	A320-28-1086/7	Modification of fuel probes	31122004
F-2002-221		30.4.2002	A320-28-1093	Wing fuel tanks pump wiring short-circuit	30042004
F-2002-259		15.4.2002	A320-53-1032R2	Fastener holes around emergency exits	X
F-2002-260		15.5.2002	A320-53-1034R2	Inspection of frame 46/stringer 37 intersection	X
F-2002-337	R1	24.7.2002	Rohr RA32078-112	Thrust reverse piston rod chrome plating	X
F-2002-340		26.6.2002	A320-57-1051R4	Inspection of junction fuselage/wing fittings	X
F-2002-365		26.6.2002	A320-24-1092R4	Test after relay 11QG relocation	X
F-2002-418		7.8.2002	A320-53A1162	Inspection of floor crossbeam	X
F-2002-453	R1	11.6.2003	A320-49-1057	APU APS 3200 exhaust tailpipe II	30062003
F-2002-456	R1	28.5.2003	A320-49-1057	APU APIC APS 3200 exhaust tailpipe	30062003
F-2002-458(B)	R2	29.10.2002	A320-34A1262R1	Thales Avionics DDRMI failure	09112002
F-2002-476	R1	21.1.2004	A320-28-1103R1	Additional electrical bonding in fuel tanks	31122007
F-2002-514	R1	13.11.2002	AMM27-34-00-200-	Elevator vibrations	31032003/1
F-2002-531		30.10.2002	A320-57-1020R1	Inspection of wing rear spar	X
F-2002-554		13.11.2002	A320-24-1099	Replacement of transformer rectifier unit	31032004
F-2002-586	R1	12.4.2003	A320-34-1263	Thales avionics pitot probes	X
F-2003-119		29.3.2003		Fuel leak procedure	29032003
F-2003-147	R1	16.4.2003	SB320-53-1147R2	Overwing emergency exit door frame corners	(3500 J)
F-2003-270		23.7.2003	-34-1231/1249/	Navigation - inertial reference systems	23072003
F-2003-434		10.12.2003	A320-52A§1086/96	MLG door actuator fitting	X
F-2004-019		4.2.2004	A320-24-1106	Hamilton Sundstrand APU generator	30102005
F-2004-032		18.2.2004	MPDSection 9-1R6	Life limits/monitored parts - MPD Section 9-1	X
F-2004-072		26.5.2040	A320-25-1338	PAX door emergency escape slides	30062007
F-2004-073		26.5.2004	A320-92-1032	Fuel - prevention against explosion risk	31122005
F-2004-120		31.7.2004	A320-28-1123	Fuel system air release valve	30062007
F-2004-121	R1	23.10.2004	A320-33-1041	Emergency escape path marking	31122005
F-2004-122		31.7.2004	A320-27-1158/9	Spoiler actuators	31072005
F-2004-123	R1	2.7.2005	A320-21-1141	Cargo compartment heating temp. sensor	31052007
F-2004-129		14.8.2004	A320-92-1007R8	Cable segregation around rack 90 VU	05082005
F-2004-137		20.11.2004	A320-32-1201R1	Parking brake system	31032009
F-2004-150		11.9.2004	A320-29-1111	Airborne ground check module	31072007
F-2004-168	R1	20.10.2004	A320-34-1335	Loss of integrated standby instrument system	23102004
F-2004-172	R1	23.4.2005	A320-52-1124	Cargo compartment water drain valves	31122005
F-2004-173		6.11.2004	A320-24-1062R5	Fule system electrical cables	31122009
F-2004-189	R1	5.1.2005	A320-53A1158	MLG door actuator fitting	X
F-2005-013		29.1.2005	A320-27-1149	Flight controls - ELA C 1 computer	29012005
F-2005-031		26.2.2005	A320-28-1008R1	Impovement of cables around fuel pumps	31122009
F-2005-040		12.3.2005	AMM25-28-12/42	Non-textile floor (NTF) replacement	31122009
F-2005-056		23.4.2005	A320-28-1067R2	Explosion risks in fuel tank bonding	31122009
F-2005-057		23.4.2005	A320-52-1112	PAX door slide raft telescopic girt bar	31122006

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
F-2005-058	23.4.2005	A320-28-1055R1	Explosion risk in fuel tank bonding	31122009
F-2005-101	2.7.2005	CMR	Certified limitations - MPD section 9-3	X
F-2005-108	16.6.2005	A320-28-1138	Fuel system - Magnetic fuel level indicator (MF	31122010
F-2005-115	16.6.2005	A320-32A1273 R2	Main landing gear (MLG)	AD
F-2005-128	13.7.2005	AOT A320-32A1303	Main landing gear (MLG) axle nut separation	X
F-2005-164	8.10.2005	TAAI1-25-617	Cockpit seats actuators inspection	31052010
F-2005-165	8.10.2005		Fuel leak procedure	08102005
F-2005-172	31.12.2005	A320-25-1394R1	Forward passenger doors - Escape slide raft	X
F-2005-173	5.11.2005	A320-28-1059R6	Fuel system - Prevention against explosion ris	X
F-2005-189	3.12.2005	A320-28-1122	Fuel system - Twin motor low pressure valve a	X
F-2005-212	31.12.2005	A320-29-1124	Ram air turbine carbon blade	X
<b>A321-211</b>				
EASA2006-0135	5.6.2006	AFMTR2.05.00/67	Speed limitation when Ram Air Turbine deploy	jp
EASA2006-0136	5.6.2006	A320-54A1015R2	Engine Pylon Spar Box Ribs	jp
EASA2006-0153	R2 26.6.2006	A320-49-1068R1	APU starter motor and air intake system inspe	Read AD
EASA2006-0328	2.11.2006	C20452-32-3254	Main Landing Gear Wheel Assembly - Inspecti	Read AD
EASA2007-0036	R1 16.2.2007	A320-71A1042R1	Forward Engine Mount Bolts - Inspection/Repl	Read AD
EASA2007-0064	R1 5.10.2007	SB A320-57-1121	Dry bay skin inspection	27.11.2008
EASA2007-0065	R2 14.3.2011	Read AD	Extension and retraction selector valves inspe	Read AD
EASA2007-0161	25.6.2007	A320-53-1195/6	Inspection MLG door keel beam hinge & actua	X
EASA2007-0162	26.5.2007	A320-57-1100/1	Inspection of wing rear spar	5500FC/10
EASA2007-0163	25.6.2007	A320-27-1132R1	Inspection of elevator backlash	20KK
EASA2007-0214	21.8.2007	A320-25-1535	103VU box hinge pin stopper modification	31.3.2009
EASA2007-0217	23.8.2007	Read AD	Northrop-Grumman ADIRU replacement	Read AD
EASA2007-0218	R1 14.3.2011	SB A320-28-1159	Fuel pumps airworthiness limitations / inspecti	7.9.2007
EASA2007-0249	8.10.2007	SB A320-26A1068	Inspection of fire extinguishing circuit system	600 FH
EASA2007-0276	R1 18.3.2010	Read AD	80VU rack attachments inspection / repair / r	Read AD
EASA2007-0286	28.11.2007	SB A320-33-1057	Emergency lighting for stand-by instruments m	27.11.2011
EASA2008-0032	6.3.2008	Read AD	EIS2 standard S7 installation	Read AD
EASA2008-0048	13.3.2008		Braking and steering control unit modification	X
EASA2008-0150	19.8.2008	A320-27-1164R6	Trimmable horizontal stabilizer actuator	10KK/20KK
EASA2008-0151	19.8.2008	A320-25-1444	Cockpit door latch/striker assembly	31032009
EASA2008-0191-E	21.10.2008	AOT A320-71A1045	Rear engine mount barrel nuts inspection	28.10.2008
EASA2008-0198	18.11.2008	SB A320-31-1286	EIS DMC software update	30.11.2013
EASA2009-0025	24.2.2009	Read AD	Flap track no.1 pendulum assembly inspection	600FH
EASA2009-0141	16.7.2009	AOT A320-55A1038	Inspection of rudder side shell skin	SEE AD
EASA2009-0235	12.11.2009	A320-24-1120R3	Modification of AC and DC ESS power supply	12112013
EASA2009-0252	10.12.2009	Read AD	Door modification	Read AD
EASA2010-0027	5.3.2010	A320-28A1173	Fuel tank harness ring tags inspection	600FH
EASA2010-0046	2.4.2010	Read AD	Elevator servo-control rod eye-end inspection	Read AD

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2010-0071		29.4.2010	See AD	Damage tolerant airworthiness limitations	SEE AD
EASA2010-0071	R1	11.6.2010	Read AD	Damage tolerant airworthiness limitation items	Read AD
EASA2010-0091	R1	26.10.2010	A320-55A1040	Elevators inspection	Read AD
EASA2010-0120		5.7.2010	AOT A320-29A1150	Hamilton Sundstrand ram air turbine balance w	Read AD
EASA2010-0148		4.8.2010	Read AD	DASELL lavatory walls inspection/repair	26.6.2006
EASA2010-0164		19.8.2010	Read AD	Rudder side shell skin inspection	1.2.2010
EASA2010-0177		13.9.2010	A320-28-1162r01	Additional centre tanks manhole cover seal rep	Read AD
EASA2010-0209		28.10.2010	A320-57-1133R5	Inboard flap trunnion and sliding panel inspecti	SEE AD
EASA2011-0001		24.1.2011	A320-31-1334R2	Replacement of flight warning computers	X
EASA2011-0011		4.2.2011	A320-57A1166	MLG support rib 5 fitting	SEE AD
EASA2011-0024	R1	14.3.2011	Read AD	MLG side-stay cuff lug inspection / repair	Read AD
EASA2011-0034		16.3.2011	A320-57-1152	Outer wing refuelling aperture electrical bondin	16.3.2013
EASA2011-0035		16.3.2011	A320-57-1120 R1	Centre wing box lower panel inspection	Read AD
EASA2011-0054		7.4.2011	A320-92A1072	Replacement of terminal modules in electronic	X
EASA2011-0069		2.5.2011		Main landing gear door actuator - monitoring/in	Read AD
EASA2011-0077		19.5.2011	A320-25-1294 r6	Cargo loading system fixed YZ latches attache	19.1.2013
EASA2011-0120	R1	27.7.2011	A320-53-1218	Nuts Inspection/Replacement	Read AD
EASA2011-0121	R1	27.7.2011	A320-57-1153	Nuts Inspection / Replacement	Read AD
EASA2011-0137		4.8.2011	A320-25A1757	PAX compartment class divider gas spring da	04112011
EASA2011-0142		25.7.2011	AFM TR112	Display unit failure operational procedure	18.8.2011
EASA2011-0155		8.9.2011	ALS Part 5	Fuel airworthiness limitations	X
EASA2011-0160		9.9.2011	A320-25-1723/4	Replacement of escape slide raft	09092014
EASA2011-0167		20.9.2011	A320-35A1047	Modification of chemical emergency oxygen co	20052013
EASA2011-0201		27.10.2011	Read AD	Inspection of NLG braking & steering control u	Read AD
EASA2011-0202		27.10.2011	Read AD	Landing gear control and interface unit wiring -	Read AD
EASA-2011-0203		27.10.2011	SB A320-34-1452	Replacement of angle of attack probes	27102012
EASA2011-0203		27.10.2011	SB A320-34-1452	Angle of attack (AoA) probes - replacement	27.10.2012
EASA2011-0229		20.12.2011	A320-53-1247	Forward fuselage frame (FR) 24 - inspection/m	24000 FCS
EASA2011-0231		23.12.2011	A320-53-1245R1	Windshield central lower node continuity fitting	X
F-1996-271-092	R3	11.8.1999	A320-27-1108R3	Inboard flap trunnion	X
F-1997-203-102	R1	8.4.1998	A320-30-1036	Probe heat computer	X
F-1998-178-115		6.5.1998	A320-25-1186	Improvement of avionic protection	X
F-1998-226-119	R1	12.1.2000	A320-22--1045/6	Automatic landing limitations	X
F-1998-292-117		29.7.1998	A320-25-1199	Emergency escape slide	X
F-1998-341	R1	23.9.1998	A320-25-1208	Sicma aero seats	X
F-1998-451-121		18.11.1998	A320-34-1163	ILS receiver	X
F-1998-482-122	R1	21.4.1999	A320-52-1094R1	Passenger & emergency door act.	X
F-1999-051-125		10.2.1999	A320-53-1130	Rear fuselage reinforcement	X
F-1999-124-129		24.3.1999	A320-32-1197	Nose landing gear wheel rotation	X
F-1999-148-130		7.4.1999	A320-52-1057R6	Passenger door safety pin greasing	X

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
F-1999-361-138		8.9.1999	A320-34-1191/6	Litton GPSSU	X
F-1999-362-139		18.9.1999	A320-27-1126/7	Spoiler servocontrols	30101999
F-1999-411-140	R1	3.5.2000	A320-22-1063	FMGC new calculator	X
F-1999-412-141		20.10.1999	A320-29-1088	RAT actuator	X
F-2000-004-142		12.1.2000	A320-34-1030/1	Rockwell Collins radio altimeter	X
F-2000-256-145		14.6.2000	A320-25-120	Sliding footrest improvement	X
F-2000-258-146		14.6.2000	A320-32-1199/0	BDDV check & modification	X
F-2000-359-152	R2	23.2.2001	A320-25-1215	Emergency escape slides	X
F-2000-372-151		6.9.2000	A320-27-1042	Stiff rudder pedal	X
F-2000-428-153	R1	29.11.2000	A320-32-1119	Main landing gear pintle pin cross bolt	X
F-2000-518-157		13.12.2000	A320-56-1007	Cockpit sliding window mechanism	X
F-2000-519-158		13.12.2000	AOT52A1106	Passenger door outer handle	X
F-2000-520-159		13.12.2000	A320-55A1027R1	Vertical stabilizer spar box	X
F-2000-524		27.12.2000	TAA12-25-402R1	SOGERMA flight crew seats	X
F-2001-062		21.2.2001	A320-55-1024	Reprotection of the elevator against water	X
F-2001-063		21.2.2001	A320-52-1102R1	PAX door slide raft girt bar	X
F-2001-100		21.3.2001	A320-52-1057	PAX door upper safety pin	X
F-2001-237	R1	25.7.2001	A320-35-1003/.16	Crew oxygen supply	31102002
F-2001-362		8.8.2001	A320-34-1127	Pitot probes	08082003
F-2001-363		8.8.2001	A320-35-1022	Oxygen passenger containers	X
F-2001-384	R1	20.3.2002	ASB320-32A1233	Yellow hydraulic circuit - PBOV	(ASB)/3112
F-2001-606		12.12.2001	A320-56A1010R1	PPG Aerospace windshields	30062002
F-2001-632		26.12.2001	A320-56-1009	Cockpit windows outer ply separation	(500H)
F-2001-634		26.12.2001	A320-53-1154	Rear PAX door frame upper guide rod fitting	31102003
F-2002-074	R1	20.3.2002	A320-32-1229	MLG crashworthiness pin	30062004
F-2002-202		17.4.2002	A320-28-1077R4	Electrical bonding in fuel tanks	31122004
F-2002-221		30.4.2002	A320-28-1093	Wing fuel tanks pump wiring short-circuit	30042004
F-2002-337	R1	24.7.2002	Rohr RA32078-112	Thrust reverse piston rod chrome plating	X
F-2002-365		26.6.2002	A320-24-1092R4	Test after relay 11QG relocation	X
F-2002-418		7.8.2002	A320-53A1162	Inspection of floor crossbeam	X
F-2002-453	R1	11.6.2003	A320-49-1057	APU APS 3200 exhaust tailpipe II	30062003
F-2002-456	R1	28.5.2003	A320-49-1057	APU APIC APS 3200 exhaust tailpipe	30062003
F-2002-458(B)	R2	29.10.2002	A320-34A1262R1	Thales Avionics DDRMI failure	09112002
F-2002-514	R1	13.11.2002	AMM27-34-00-200-	Elevator vibrations	31032003/1
F-2002-554		13.11.2002	A320-24-1099	Replacement of transformer rectifier unit	31032004
F-2002-586	R1	12.4.2003	A320-34-1263	Thales avionics pitot probes	X
F-2003-119		29.3.2003		Fuel leak procedure	29032003
F-2003-270		23.7.2003	-34-1231/1249/	Navigation - inertial reference systems	23072003
F-2003-434		10.12.2003	A320-52A§1086/96	MLG door actuator fitting	X
F-2004-019		4.2.2004	A320-24-1106	Hamilton Sundstrand APU generator	30102005

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
F-2004-032		18.2.2004	MPDSection 9-1R6	Life limits/monitored parts - MPD Section 9-1	X
F-2004-040		31.3.2004	A320-52-1121	Hold open mechanism of emergency exit door	31012006
F-2004-072		26.5.2040	A320-25-1338	PAX door emergency escape slides	30062007
F-2004-073		26.5.2004	A320-92-1032	Fuel - prevention against explosion risk	31122005
F-2004-120		31.7.2004	A320-28-1123	Fuel system air release valve	30062007
F-2004-121	R1	23.10.2004	A320-33-1041	Emergency escape path marking	31122005
F-2004-122		31.7.2004	A320-27-1158/9	Spoiler actuators	31072005
F-2004-123	R1	2.7.2005	A320-21-1141	Cargo compartment heating temp. sensor	31052007
F-2004-129		14.8.2004	A320-92-1007R8	Cable segregation around rack 90 VU	05082005
F-2004-137		20.11.2004	A320-32-1201R1	Parking brake system	31032009
F-2004-147		28.8.2004	A320-27-1151/2	Flight controls in landing configuration	31.12.2005
F-2004-168	R1	20.10.2004	A320-34-1335	Loss of integrated standby instrument system	23102004
F-2004-172	R1	23.4.2005	A320-52-1124	Cargo compartment water drain valves	31122005
F-2004-189	R1	5.1.2005	A320-53A1158	MLG door actuator fitting	X
F-2005-040		12.3.2005	AMM25-28-12/42	Non-textile floor (NTF) replacement	31122009
F-2005-057		23.4.2005	A320-52-1112	PAX door slide raft telescopic girt bar	31122006
F-2005-058		23.4.2005	A320-28-1055R1	Explosion risk in fuel tank bonding	31122009
F-2005-101		2.7.2005	CMR	Certified limitations - MPD section 9-3	X
F-2005-108		16.6.2005	A320-28-1138	Fuel system - Magnetic fuel level indicator (MF	31122010
F-2005-115		16.6.2005	A320-32A1273 R2	Main landing gear (MLG)	AD
F-2005-155		31.8.2005	A320-25-1416	Escape slide failure at doors 2 and 3	09092005
F-2005-164		8.10.2005	TAAI1-25-617	Cockpit seats actuators inspection	31052010
F-2005-165		8.10.2005		Fuel leak procedure	08102005
F-2005-172		31.12.2005	A320-25-1394R1	Forward passenger doors - Escape slide raft	X
F-2005-189		3.12.2005	A320-28-1122	Fuel system - Twin motor low pressure valve a	X
F-2005-212		31.12.2005	A320-29-1124	Ram air turbine carbon blade	X
<b>A330</b>					
EASA2007-0070	R1	25.11.2010	Read AD	NW steering system rotating sleeve inspection	Read AD
EASA2008-0161	R1	21.3.2009	Read AD	Passenger compartment electrical harness mo	22.8.2010
EASA2008-0173	R1	22.10.2010	Read AD	APU generator inspection	450FH/200
EASA2009-0075		20.4.2009	A330-73-3049	IPTOS protection function activation	30.6.2009
EASA2009-0076		20.4.2009	Read AD	Electric routing modification	20.4.2011
EASA2009-0077		20.4.2009	Read AD	Hat-rack connectors modification	20.4.2011
EASA2009-0138		8.7.2009		Main landing gear pin W1 replacement	11150 TotL
EASA2009-0150		23.7.2009	A330-21-3148	Modification of air cooling heat shield	23072011
EASA2009-0195		7.9.2009	Read AD	Airspeed pitot probes replacement	7.1.2010
EASA2009-0204		14.10.2009	A330-71-3022	Engine mount link pin retention bolts inspectio	4500/2500F
EASA2009-0237-E		2.11.2009	Read AD	Oxygen containers inspection	150FH
EASA2009-0240		19.11.2009	A330-71-3020	Fwd and aft mount pylon bolts inspection	8000FC/24
EASA2009-0252		10.12.2009	Read AD	Door modification	Read AD

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2009-0255		15.12.2009	A330-55-3039	Inspection of elevators	X
EASA2009-0260		24.12.2009	Read AD	RAT balance weight screws inspection	Read AD
EASA2010-0016	R1	10.2.2010	Read AD	Thales Avionics AoA probe inspection	30.4.2010
EASA2010-0018		18.2.2010	SB A330-28-3111	Wing fuel tank pressure switch replacement	18.2.2015
EASA2010-0021		23.2.2010	Read AD	Rudder side shell skin inspection	31.7.2009
EASA2010-0024		26.2.2010	Read AD	Keel beam fastener holes at frame FR40 inspe	Read AD
EASA2010-0034		19.3.2010	A330-32-3233	Inspection of NLG main fitting and sliding tube	900FH
EASA2010-0081		11.5.2010	Read AD	Elevator servo controls solenoid valve o-ring re	Read AD
EASA2010-0083-C		20.9.2010	N/A	Fuel pump NRV operational test	N/A
EASA2010-0086	R1	17.6.2010	Read AD	Hydraulic pump electrical motor connectors m	Read AD
EASA2010-0089		24.5.2010	Read AD	Flight Warning Computer (FWC) software insta	24.11.2010
EASA2010-0103	R1	12.4.2011	Read AD	Cable loom installation - modification	23.06.2012
EASA2010-0109		12.7.2010	Read AD	Flight control primary computer dispatch restri	12.7.2010
EASA2010-0127		7.7.2010	Read AD	Rudder side shell skin inspection	Read AD
EASA2010-0132		12.7.2010	A330-28A3114	Water scavenge system deactivation / dispatc	Read AD
EASA2010-0135		19.7.2010	Read AD	Girt bar slider mechanism functional check an	Read AD
EASA2010-0173		31.8.2010	A330-53-8185	Fuselage internal structure at frame 39.1 - insp	Read AD
EASA2010-0174		31.8.2010		Damage tolerant airworthiness limitation items	Read AD
EASA2010-0187		21.9.2010	A330-78-3006	Thrust reverser opening mechanism inspection	1200/2000F
EASA2010-0191		27.9.2010	Read AD	FCPC PRIM 3 dispatch restriction	11.10.2014
EASA2010-0192		13.10.2010	A330-27-3102	Horizontal Stabilier actuator screw/nut assemb	see AD
EASA2010-0205		22.10.2010		Replacement of MLG retraction bracket	X
EASA2010-0252		13.12.2010	A330-53-3183	Inspection of fuselage nuts	X
EASA2010-0253		17.12.2010	ALS Part 1	Safe life airworthiness limitations items	X
EASA2010-0264		3.1.2011	ALS Part 3 R3	Amendment of ALS Part 3	X
EASA2010-0267		4.1.2011	AOT A330-27A3174	Operational test of wing tip brakes	04042011
EASA2010-0271		5.1.2011	OEB82/1, 95/1	Operational procedures at auto flight disconne	20012011
EASA2011-0007	R1	28.2.2011	Read AD	Forward and aft cargo compartment doors insp	Read AD
EASA2011-0018		17.2.2011	A330-78-3010	Life limit of thrust reverser C-ducts	See AD
EASA2011-0032		15.3.2011	Read AD	Nose landing gear main fitting modification	Read AD
EASA2011-0040		22.3.2011	A330-32-3240	Inspection of main & central LG bogie pivot pin	22052013
EASA2011-0073		4.5.2011	Read AD	Fire detection unit - inspection/replacement	1000 FH
EASA2011-0122-E		29.6.2011	Read AD	Main Landing Gear (MLG) Bogie Beam Life Li	Read AD
EASA2011-0138		3.8.2011	AOT330-34A3235R1	Pitot probe quick-disconnect union	X
EASA2011-0139		8.8.2011	AOT A330-29A3111	Inspection of HP manifold check valves	X
EASA2011-0141		25.7.2011	Read AD	Main Landing Gear (MLG) Bogie Beam Inspect	Read AD
EASA2011-0170		21.9.2011	AOTA330-32A-3256	Reduced life limit of MLG wheel axle following	read AD
EASA2011-0171		21.9.2011	A330-53-3193	Insp. Of frame (FR) 40 / fuselage skin panel ju	read AD
EASA2011-0177		29.9.2011	A330-52-3083	Inspection of forward and aft cargo doors	X
EASA2011-0179		30.9.2011	Read AD	Main landing gear retraction actuator piston ro	Read AD

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2011-0196	21.10.2011	SBA330-28-3113	Modification of fuel pump control circuit	21102015
EASA2011-0197	24.10.2011	A330-29-3117	Replacement of RAT pump anti-stall device	Read AD
EASA2011-0199	10.11.2011	Read AD	Flight control primary computer - modification/r	(10.9.2012)
EASA2011-0204	28.10.2011	A330-29-3114	Replacement of ram air turbine actuator	28102014
EASA2011-0211	14.11.2011	Read Ad	MLG bogie beam inspection/replacement	Read AD
EASA-2011-0212	14.11.2011	A330 ASL Part 1	MLG bogie beam life limit	Read AD
EASA2011-0242	2.1.2012	A330-56-3009R1	Inspection of windshield heating connectors	X
<b>A340</b>				
EASA2006-0196	17.7.2006	A340-31-4100	Periodic reset & modification of display units	23092005
EASA2006-0205	19.7.2006	FAL95A.1933/05	Fuel tank safety	19102006
EASA2006-0225	4.8.2006	A340CMR issue 14	Certification maintenance requirements	04082006
EASA2006-0309	R1 21.11.2006		Exhaust-Thrust Reverser "J-Ring" - Mod	X
EASA2006-0309F	25.10.2006	A340-78-4031R01	Exhaust-Thrust Reverser "J-Ring" - Mod	X
EASA2006-0333	6.11.2006	Read AD	Fuselage skin inspection/repair	X
EASA2006-0354	12.12.2006	Read AD	Slide Rafts Fitted on Type A Doors - Modificati	X
EASA2006-0364-E	6.12.2006	Read AD	Main Landing Gear (MLG) Rib 6 Aft Bearing Lu	Read AD
EASA2007-0008	23.1.2007	A340-27-4135	Test/modification of elevator servo controls	30062008
EASA2007-0011	23.1.2007	A340-27-4131/-29	Inspection of elevator servo controls transduce	X
EASA2007-0080	R1 17.4.2007	Read AD	Auxiliary Power Unit - Oil pump module - Inspe	X
EASA2007-0125	18.5.2007	A340-53-4175	Longitudal joint at stringer 28 RH between FR1	X
EASA2007-0146	5.6.2007	A340-57-4093	Wing - LH & RH Wing rib 6 - Inspection/Modifi	Read AD
EASA2007-0188-E	16.7.2007		APU Generator inspection	26.7./450F
EASA2007-0239	17.9.2007	Read AD	Refuel isolation valve replacement	18000 FH
EASA2007-0246	19.9.2007	Read AD	Rudder control rod inspection	600 FH
EASA2007-0247-E	R1 10.9.2007	Read AD	MLG bearing lug inspection	Read AD
EASA2007-0250-E	12.9.2007	AOT A340-78A034	Thrust reverser pivoting door actuator attachm	14092007
EASA2007-0269	R1 24.10.2007	Read AD	Rear fuselage modification	Read AD
EASA2007-0278	19.11.2007	Read AD	Prevention against fuel explosion risks	Read AD
F-2000-524	27.12.2000	TAA12-25-402R1	SOGERMA flight crew seats	X
F-2001-606	12.12.2001	A320-56A1010R1	PPG Aerospace windshields	30062002
F-2005-040	12.3.2005	AMM25-28-12/42	Non-textile floor (NTF) replacement	31122009
F-2005-164	8.10.2005	TAA11-25-617	Cockpit seats actuators inspection	31052010
<b>A340-300</b>				
EASA200-0193	13.10.2010	A340-27-4107R08	Horizontal Stabilier actuator screw/nut assemb	see AD
EASA2006-0298	R1 23.10.2006	A340-78-4032 R2	Thrust reverser outer fixed structure modificati	Read AD
EASA2007-0069	R1 25.10.2010	Read AD	NW steering system rotating sleeve inspection	Read AD
EASA2007-0282	20.11.2007	Read AD	Cockpit instrument panel inspection	Read AD
EASA2007-0284	26.11.2007	Read AD	Longitudinal doubler at VTP attachment cut-ou	Read AD
EASA2007-0302	28.12.2007	Read AD	Forward fuselage frame 12 inspection	19500 FC
EASA2007-0308	2.1.2008	Read AD	Trimmable horizontal stabilizer actuator (THSA	Read AD

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2008-0002		21.1.2008	Read AD	Wing shroud box bottom panel modification	31.10.2013
EASA2008-0012		28.1.2008	Read AD	CFRP rudder inspection	Read AD
EASA2008-0026		26.2.2008	Read AD	Flap down drive shaft inspection	Read AD
EASA2008-0050		18.3.2008	Read AD	Frame foot junction inspection	Read AD
EASA2008-0140		11.8.2008	A340-54-4010	Inspection of pylon pyramid attachment area	SEE AD
EASA2008-0153		22.8.2008	A340-57-4103R1	Movable flap track fairing 3	22082013
EASA2008-0160		5.9.2008	Read AD	Spoiler servo control maintenance cover modifi	3kk/9kk
EASA2008-0161	R1	21.3.2009	Read AD	Passenger compartment electrical harness mo	22.8.2010
EASA2008-0173	R1	22.10.2010	Read AD	APU generator inspection	450FH/200
EASA2008-0210		17.12.2008	Read AD	Separation of IFS panels-temp monitoring	Read AD
EASA2009-0001		22.1.2009	Read AD	Frame 40 rear fitting web inspection	Read AD
EASA2009-0012-E		19.1.2009	Read AD	ADIRU operational procedure	19.1.2009
EASA2009-0056		25.3.2009	Read AD	Thrust reverser "J-Ring" beam inspection	Read AD
EASA2009-0063		25.3.2009	AOT A340-78A4040	Adjustment of thrust reverser	X
EASA2009-0064		26.3.2009	A340-26-4038	Replacement of fire extinguishing system	26.9.2010
EASA2009-0076		20.4.2009	Read AD	Electric routing modification	20.4.2011
EASA2009-0077		20.4.2009	Read AD	Hat-rack connectors modification	20.4.2011
EASA2009-0108		19.5.2009	A340-71-4007	Fwd engine mount thrust links inspection	Read AD
EASA2009-0115		12.6.2009	A340-71-4006	Forward engine mount thrust links replacemen	15.6.2009
EASA2009-0133		7.7.2009	SB A340-78-4039	TR aux return line hose assembly replacement	7.7.2011
EASA2009-0138		8.7.2009		Main landing gear pin W1 replacement	11150 TotL
EASA2009-0150		23.7.2009	A330-21-3148	Modification of air cooling heat shield	23072011
EASA2009-0195		7.9.2009	Read AD	Airspeed pitot probes replacement	7.1.2010
EASA2009-0201		24.9.2009	Read AD	Reading light wiring disconnection	24.12.2009
EASA2009-0237-E		2.11.2009	Read AD	Oxygen containers inspection	150FH
EASA2009-0252		10.12.2009	Read AD	Door modification	Read AD
EASA2009-0255		15.12.2009	A330-55-3039	Inspection of elevators	X
EASA2009-0260		24.12.2009	Read AD	RAT balance weight screws inspection	Read AD
EASA2010-0016	R1	10.2.2010	Read AD	Thales Avionics AoA probe inspection	30.4.2010
EASA2010-0021		23.2.2010	Read AD	Rudder side shell skin inspection	31.7.2009
EASA2010-0024		26.2.2010	Read AD	Keel beam fastener holes at frame FR40 inspe	Read AD
EASA2010-0034		19.3.2010	A330-32-3233	Inspection of NLG main fitting and sliding tube	900FH
EASA2010-0036		22.3.2010	A340 ALI	Damage tolerant airworthiness limitations - AL	X
EASA2010-0044		31.3.2010	Read AD	Thrust reverser actuation system doors replac	28.2.2011
EASA2010-0047		2.4.2010		ALS part 3 amendment	Read AD
EASA2010-0081		11.5.2010	Read AD	Elevator servo controls solenoid valve o-ring re	Read AD
EASA2010-0083-C		20.9.2010	N/A	Fuel pump NRV operational test	N/A
EASA2010-0086	R1	17.6.2010	Read AD	Hydraulic pump electrical motor connectors m	Read AD
EASA2010-0089		24.5.2010	Read AD	Flight Warning Computer (FWC) software insta	24.11.2010
EASA2010-0103	R1	12.4.2011	Read AD	Cable loom installation - modification	23.06.2012

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2010-0109	12.7.2010	Read AD	Flight control primary computer dispatch restri	12.7.2010
EASA2010-0127	7.7.2010	Read AD	Rudder side shell skin inspection	Read AD
EASA2010-0135	19.7.2010	Read AD	Girt bar slider mechanism functional check an	Read AD
EASA2010-0191	27.9.2010	Read AD	FCPC PRIM 3 dispatch restriction	11.10.2014
EASA2010-0205	22.10.2010		Replacement of MLG retraction bracket	X
EASA2010-0211	R1 6.12.2010	A340-54A4011	Outboard PEF shutter flap inspection	2000FH
EASA2010-0232	26.11.2010	A340-28-4097R5	Prevention against fuel explosion risks	26112012
EASA2010-0245	10.12.2010	A340-53-4184	Inspection of fuselage frame 39.1	7850FC/53
EASA2010-0253	17.12.2010	ALS Part 1	Safe life airworthiness limitations items	X
EASA2010-0267	4.1.2011	AOT A330-27A3174	Operational test of wing tip brakes	04042011
EASA2010-0271	5.1.2011	OEB82/1, 95/1	Operational procedures at auto flight disconne	20012011
EASA2011-0007	R1 28.2.2011	Read AD	Forward and aft cargo compartment doors insp	Read AD
EASA2011-0032	15.3.2011	Read AD	Nose landing gear main fitting modification	Read AD
EASA2011-0040	22.3.2011	A330-32-3240	Inspection of main & central LG bogie pivot pin	22052013
EASA2011-0073	4.5.2011	Read AD	Fire detection unit - inspection/replacement	1000 FH
EASA2011-0122-E	29.6.2011	Read AD	Main Landing Gear (MLG) Bogie Beam Life Li	Read AD
EASA2011-0138	3.8.2011	AOT330-34A3235R1	Pitot probe quick-disconnect union	X
EASA2011-0139	8.8.2011	AOT A330-29A3111	Inspection of HP manifold check valves	X
EASA2011-0141	25.7.2011	Read AD	Main Landing Gear (MLG) Bogie Beam Inspect	Read AD
EASA2011-0170	21.9.2011	AOTA330-32A-3256	Reduced life limit of MLG wheel axle following	read AD
EASA2011-0171	21.9.2011	A330-53-3193	Insp. Of frame (FR) 40 / fuselage skin panel ju	read AD
EASA2011-0174	22.9.2011	A340-78-4041	Replacement of thrust reverser outer fixed stru	X
EASA2011-0178	30.9.2011	Read AD	Main Landing gear retraction actuator piston ro	Read AD
EASA2011-0196	21.10.2011	SBA330-28-3113	Modification of fuel pump control circuit	21102015
EASA2011-0197	24.10.2011	A330-29-3117	Replacement of RAT pump anti-stall device	Read AD
EASA2011-0199	10.11.2011	Read AD	Flight control primary computer - modification/r	(10.9.2012)
EASA2011-0204	28.10.2011	A330-29-3114	Replacement of ram air turbine actuator	28102014
EASA2011-0211	14.11.2011	Read Ad	MLG bogie beam inspection/replacement	Read AD
EASA2011-0238	28.12.2011		Aft lower pylon fairing attachement - inspection	X
EASA2011-0242	2.1.2012	A330-56-3009R1	Inspection of windshield heating connectors	X

### **ATR-GIE Avions de Transport Régional**

#### **ATR-42**

EASA2006-0216	17.7.2006	Dowty 631-32-190	Cross locking bolt of the MLG attachment pin	01082006
EASA2006-0283	28.9.2006	Read AD	120 VU electrical harness inspection	31.12.2006
EASA2006-0303	25.10.2006	Read AD	Vertical stabilizer fin tip - Inspection/Repair/Mo	Read AD
EASA2006-0376	2.1.2007	Read AD	Aileron Tab Bellcrank Assembly - Inspection	X
EASA2007-0106-E	20.4.2007	ATR42-25-0155	Removal of thermal-acoustical insulation blank	05052007
EASA2007-0112	11.5.2007	MDSB63§1-32-191R	Inspection of MLG side brace assembly upper	2600FC
EASA2007-0164	28.6.2007	ATR72-25-1074R2	Replacement of thermal insulation blankets	31052009
EASA2007-0179	14.8.2007	ATR72-30-1044	inspection of pitot probe resistance	(550H)

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2007-0226	R1	24.11.2009	Read AD	Fuel tank system wiring & sensors modificatio	28.8.2011
EASA2007-0263		17.10.2007	Read AD	Landing gear side brace inspection	Read AD
EASA2008-0062		15.4.2008	ATR72-92-1016	Electrical wires in the rear bulkhead area	X
EASA2008-0124		18.7.2008	Read AD	Use of flaps 45 deg configuration prohibition	25.7.2008
EASA2008-0218		24.12.2008	Read AD	Wire bundles in the rear baggage zone protecti	550 FH
EASA2009-0159-E		22.7.2009	NP-158862-001	Cockpit forward side windows inspection	Read AD
EASA2009-0170		24.8.2009	Read AD	MPC with APM function installation	C/72kk
EASA2009-0242		1.1.2010	Read AD	CMR and CDCCL Fuel tank safety	2.3.2010
EASA2010-0061		14.4.2010	L'Hotellier SB	Halon 1211 fire extinguishers identification/repl	14.8.2010
EASA2010-0138		15.7.2010	Read AD	Elevator inboard hinge fitting lower stop angles	15.1.2011
F-2002-506	R1	24.12.2002	ATR72-55-1003R1	Fin tip upper closure rib	500H
F-2002-539		30.10.2002	ATR72-25-1082	Forward attendant seat	30042004
F-2003-106	R1	16.4.2003	ATR72-92-1010R1	Stand-by pitch trim switch	31082003
F-2005-160		8.9.2005	AOM42-72/2005/08	Fuel quantity indicator	08092005
<b>ATR-72</b>					
EASA2006-0216		17.7.2006	Dowty 631-32-190	Cross locking bolt of the MLG attachment pin	01082006
EASA2006-0283		28.9.2006	Read AD	120 VU electrical harness inspection	31.12.2006
EASA2006-0303		25.10.2006	Read AD	Vertical stabilizer fin tip - Inspection/Repair/Mo	Read AD
EASA2006-0376		2.1.2007	Read AD	Aileron Tab Bellcrank Assembly - Inspection	X
EASA2007-0164		28.6.2007	ATR72-25-1074R2	Replacement of thermal insulation blankets	31052009
EASA2007-0179		14.8.2007	ATR72-30-1044	inspection of pitot probe resistance	(550H)
EASA2007-0226	R1	24.11.2009	Read AD	Fuel tank system wiring & sensors modificatio	28.8.2011
EASA2008-0062		15.4.2008	ATR72-92-1016	Electrical wires in the rear bulkhead area	X
EASA2008-0137-E		23.7.2008	Read AD	Cotter pins and pitch uncoupling mechanism in	2.8.2008
EASA2008-0218		24.12.2008	Read AD	Wire bundles in the rear baggage zone protecti	550 FH
EASA2009-0159-E		22.7.2009	NP-158862-001	Cockpit forward side windows inspection	Read AD
EASA2009-0170		24.8.2009	Read AD	MPC with APM function installation	C/72kk
EASA2009-0242		1.1.2010	Read AD	CMR and CDCCL Fuel tank safety	2.3.2010
EASA2010-0061		14.4.2010	L'Hotellier SB	Halon 1211 fire extinguishers identification/repl	14.8.2010
EASA2010-0063-E		6.4.2010		Rudder pedal rods inspection / repair	8.4.2010
EASA2010-0138		15.7.2010	Read AD	Elevator inboard hinge fitting lower stop angles	15.1.2011
F-1990-193-032	R2	8.7.1992	ATR72-29-A1003	N/A	X
F-1990-220-034	R1	23.4.1997	ATR72-27-1013/14	Flight controls	X
F-1991-006-037		15.9.1993	ATR72-32-1001	N/A	X
F-1991-067-005		15.9.1993	ATR72-27-1015	N/A	X
F-1991-215-006		2.10.1991	ATR72-55-1001	N/A	X
F-1991-217-007	R1	22.1.1992	ATR72-76-1002R1	N/A	X
F-1991-238-009		30.10.1991	ATR72-22-1004	N/A	X
F-1992-045-011		19.2.1992		N/A	X
F-1992-084-010	R2	25.5.1994	ATR72-26-1004/5	Fire detector	X

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
F-1992-123-013		27.5.1992	ATR72-31-1006	N/A	X
F-1992-134-014	R1	19.8.1992	ATR72-27-1025R3	N/A	X
F-1992-135-015		24.6.1992	ATR72-32-1011	N/A	X
F-1992-262-016		25.11.1992	ATR72-57-1008	N/A	X
F-1992-272-017	R1	3.2.1993	ATR72-53-1026R1	N/A	X
F-1993-116	R2	5.1.1994	SB32-106	Dunlop	X
F-1994-001-018		5.1.1994	ATR72-27-1027	Flight control rods	X
F-1994-002-019		5.1.1994	ATR72-32-1021	Nose landing gear inspection	X
F-1994-065-020	R1	5.7.1995	ATR72-32-1025	Main landing gear	X
F-1994-191-022		17.8.1994	ATR72-53-1022	N/A	X
F-1994-197-023		31.8.1994	ATR72-32-1029	N/A	X
F-1994-224-024		28.9.1994	ATR72-27-1038	N/A	X
F-1995-105-026	R1	18.10.2000	Time limits	Time limits	X
F-1996-019-028		17.1.1996	ATR72-27-1044	Elevators uncoupling mechanism	X
F-1996-110-030		5.6.1996	ATR72-71-1006	Engine nacelle drain system	X
F-1996-207-031	R1	21.4.1999	ATR72-57-1015R1	De-icing procedures	X
F-1996-288-032	R1	18.12.1996	ATR72-25-1052	Forward cargo compartment nets	X
F-1996-96-029		9.5.1996	ATR72-32-1036/7	Main landing gear pins Magnaghi	X
F-1997-158-033		16.7.1997	ATR72-53-1008/44	Karman fairing panel fasteners	X
F-1997-264-034		24.9.1997	ATR72-57-1019	External wing nuts	X
F-1998-071-035		11.2.1998	ATR72-54-1011	Engine mount fouling	X
F-1998-072-036		25.2.1998	ATR72-57-1020	Flap support beams	X
F-1998-073-037		25.2.1998	ATR72-21-1048	Rotron recirculation fan	X
F-1999-015-040	R2	10.12.2003		Icing conditions - revise the AFM	X
F-1999-015-40	R1	21.4.1999		AFM revision	X
F-1999-166-041	R1	12.7.2000	ATR72-30-1032R1	Aircraft design enhancements	X
F-2000-190-042		3.5.2000	ATR72-32-1038	Landing gear uplock boxes	X
F-2000-282-050	R1	19.9.2001	ATR72-26-1014R2	Fire handles	30042002
F-2000-437-052		18.10.2000		Engine reverse control	X
F-2000-448-053	R2	19.9.2001		Appendix to flight manual	X
F-2001-045-054		3.2.2001		AFM - deicing	X
F-2001-056-055		7.2.2001	ATR72-92-1004	Wiring conduit	02032001
F-2001-142-056		18.4.2001	SB72-52-1018R1	Result of fatigue tests	X
F-2001-215-057		30.5.2001		ATPCS test selector switch	30052006
F-2001-388-058		5.9.2001	72-27-1054/1055	Normal pitch trim switches	05122001
F-2001-505-059		17.10.2001	ATR72-92-1006	Hydraulic pump power supply cables	17102002
F-2001-615-062		26.12.2001	SB72-32-1042	MLG swinging lever spacer	X
F-2002-043-065		23.1.2002	ATR72-25-1074	Thermal/acoustical insulation materials	31052009
F-2002-072-064	R1	20.3.2002	P&W C21570	HP oil pump PRV	30062004
F-2002-073-063	R2	8.1.2003	Hamilton61-21-07	Propeller pitch change system	X

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
F-2002-091-066		20.2.2002	ATR72-92-1007	Electrical rack 90VU	01092002
F-2002-506	R1	24.12.2002	ATR72-55-1003R1	Fin tip upper closure rib	500H
F-2002-539		30.10.2002	ATR72-25-1082	Forward attendant seat	30042004
F-2003-106	R1	16.4.2003	ATR 72-92-1010R1	Stand-by pitch trim switch	31082003
F-2004-164		23.10.2004	ATR72-32-1046	MLG side brace assembly	(800FC)
F-2005-160		8.9.2005	AOM42-72/2005/08	Fuel quantity indicator	08092005
<b>BAE Systems</b>					
<b>Avro 146-RJ100</b>					
CAA001-11-2002		22.1.2003	SB.22.068-70628B	Honeywell DFGC	01052005
CAA002-07-2001		19.7.2001	ISB.53-164	Fuselage external inspection	X
CAA002-09-2001		23.10.2001	ISB.53-162	Fuselage skin chafing	(4000L)
CAA003-09-2002		22.11.2002	ISB.26-065	Wiring to Pacific Scientific engine fire extinguis	X
CAA004-02-2002		22.4.2002	ISB.21-155	Pressurisation discharge valves P/N	X
CAA004-04-2001		4.6.2001	SB24-137-01691A	Vickers standby generator	31122004
CAA004-05-2001		20.6.2001	MD SB146-32-147	MLG side stay inspection	X
CAA004-08-2001		31.8.2001	ISB.32-168	Nose landing gear cap screw torque	31012002
CAA004-09-2001	R1	25.1.2002	34-240-20005AR5	Suspension of RVSM approval	X
CAA004-12-2001		22.3.2002	ISB.53-165	Corrosion at frames 15, 18, 41, 43	SB
CAA005-10-2001		19.11.2001	SB71-077-01693A	Fireproof ceramic terminal block	31072003
CAA005-12-2001		22.4.2002	SB.27-169-01692A	Elevator surface flight dampers	31012004
CAA007-02-2003		28.5.2003	ISB.28-030	Fuel quantity indication wiring	30062003
CAA007-04-2003		28.5.2003	SB.49-036-36019E	Improved APU inlet flexible duct	X
EASA2006-0061		20.3.2006	ISB29-A046	Removal from service of hydraulic accumulator	20032006/4
EASA2006-0137		6.6.2006	32-174-70676A	Nose Landing Gear - Introduction of Revised A	X
EASA2006-0138		6.6.2006		Flight Controls - Life Limitation of Lift Spoiler A	X
EASA2006-0139		6.6.2006	27-176 Rev 2	Flight Controls - Inspection of Lift Spoiler Actua	X
EASA2006-0342		23.11.2006	25-495-60730A	Flight Deck ECS Grilles - Introduction of Bolt A	X
EASA2006-0342		23.11.2006	25-495-60730A	Flight Deck ECS Grilles - Introduction of Bolt A	X
EASA2007-0058		1.3.2007	Read AD	Stabilisers - Elevator Drain Holes - Modificatio	Read AD
EASA2007-0075		3.4.2007	ISB53-191	Inspection of aft fuselage skin under APU shiel	03042008/2
EASA2007-0076		4.4.2007	ISB29-047	Inspection of hydraulic accumulators	16052007
EASA2007-0270	R1	30.10.2007	ISB 57-033	Rear spar attachment fittings inspection	30.10.2007
EASA2007-0277		19.11.2007	ISB.53-194	Undercarriage main beam bolts inspection	4000 FC
EASA2007-0303		28.12.2007	SB 53-203	Forward and aft wing links inspection	4 yrs
EASA2007-0304		28.12.2007	SB 57-a071	Top skin under rib 0 joint strap inspection	Read AD
EASA2007-0305		3.1.2008	ISB 53-152 Rev3	LH nose lg well sidewall & retraction jack attac	Read AD
EASA2007-0307		31.12.2007	ISB 53-200	Airbrake Upper Crossbeam Inspection	Read AD
EASA2008-0003		22.1.2008	ISB 53-175 R1	Wing links inspection	Read AD
EASA2008-0092	R1	27.5.2008	ISB 53-182	Frame flanges and door hinge bosses inspecti	Read AD
EASA2008-0168		16.9.2008	ISB.57-070	Wing centre section inspection	Read AD

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2008-0180	14.10.2008	ISB.53.202R1	MLG door fairing panel grommets	(8000FC)
EASA2009-0014	4.2.2009	ISB.57-072	Fixed wing leading edge and front spar structur	Read AD
EASA2009-0020	19.2.2009	Read AD	Airworthiness limitations implementation	19.5.2009
EASA2009-0046	16.3.2009	ISB.53-213	Lug plate attachment joint inspection	16.2.2011
EASA2009-0070	R1 16.7.2010	ISB.53-167 2,3,4	External forward fuselage inspection / repair	Read AD
EASA2009-0205	R1 26.1.2010	SB.27-183-36246A	Aileron interconnect cable pulley guards install	14.4.2010
EASA2010-0001-E	6.1.2010	ISB.A32-180R2	Nose landing gear inspection	6.1.2010
EASA2010-0201	19.10.2010	ISB.32-176	MLG shock absorber lower attachment pins	19102012/4
EASA2010-0202	R1 19.10.2010	ISB.32-182	Nosa landing gear main fitting inspection / repl	Read AD
EASA2011-0048	1.4.2011	BAe146 AMM ch.05	Airworthiness limitations	01072011
EASA2011-0065	21.4.2011	Sb.26-077-36250A	Inspection of baggage bay fire bottles wiring lo	21072011
EASA2011-0097	8.6.2011	ISB.53-229R1	Inspection of NLG bay LH sidewall stiffeners	(12000 FC)
EASA2011-0099	9.6.2011	ISB.21-162R1	Inspection of front and rear discharger valves f	09062012/(
EASA2011-0216	22.11.2011	SB.25-549-65372A	Modification of galley stowage installation	22112013
EASA2011-0220	25.11.2011	SB 29-048-30676A	Hydraulic fluid containment system - installatio	Read AD
G-2004-0004	26.2.2004	SB53-170	Pressure floor over MLG bay	1000L/3000
G-2004-0006	2.3.2004	SB34-371-70671A	Distance bearing indicator	02072004
G-2004-0031	4.1.2005	SB49-072-36244A	Insulation blankets on the APU exhaust	04072005
G-2005-0009	29.4.2004	ISB53-177	Inspection of center fuselage skin	29102005/
G-2005-0014	30.6.2005	ISB.27-177	Replacement of elevator bearings	31102006
G-2005-0015	29.7.2005	MM Rev. 82	Revised airworthiness limitations	29072005
G-2005-0017	29.7.2005	SB52-113R1	Inspection of MLG door hinges	X
G-2005-0018	29.7.2005	SB57-066R2	Inspection of wing flap	29072007
G-2005-0019	29.7.2005	ISB53-182	Inspection of door frame	SB
G-2005-0026	30.9.2005	SB25-459-36241A	Strengthening of the LH flying control duct	30062006
<b>Avro 146-RJ85</b>				
CAA001-11-2002	22.1.2003	SB.22.068-70628B	Honeywell DFGC	01052005
CAA002-07-2001	19.7.2001	ISB.53-164	Fuselage external inspection	X
CAA002-09-2001	23.10.2001	ISB.53-162	Fuselage skin chafing	(4000L)
CAA003-09-2002	22.11.2002	ISB.26-065	Wiring to Pacific Scientific engine fire extinguis	X
CAA004-02-2002	22.4.2002	ISB.21-155	Pressurisation discharge valves P/N	X
CAA004-04-2001	4.6.2001	SB24-137-01691A	Vickers standby generator	31122004
CAA004-05-2001	20.6.2001	MD SB146-32-147	MLG side stay inspection	X
CAA004-08-2001	31.8.2001	ISB.32-168	Nose landing gear cap screw torque	31012002
CAA004-09-2001	R1 25.1.2002	34-240-20005AR5	Suspension of RVSM approval	X
CAA004-12-2001	22.3.2002	ISB.53-165	Corrosion at frames 15, 18, 41, 43	SB
CAA005-10-2001	19.11.2001	SB71-077-01693A	Fireproof ceramic terminal block	31072003
CAA005-12-2001	22.4.2002	SB.27-169-01692A	Elevator surface flight dampers	31012004
CAA007-02-2003	28.5.2003	ISB.28-030	Fuel quantity indication wiring	30062003
CAA007-04-2003	28.5.2003	SB.49-036-36019E	Improved APU inlet flexible duct	X

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2006-0061		20.3.2006	ISB29-A046	Removal from service of hydraulic accumulator	20032006/4
EASA2006-0137		6.6.2006	32-174-70676A	Nose Landing Gear - Introduction of Revised A	X
EASA2006-0138		6.6.2006		Flight Controls - Life Limitation of Lift Spoiler A	X
EASA2006-0139		6.6.2006	27-176 Rev 2	Flight Controls - Inspection of Lift Spoiler Actuator	X
EASA2006-0342		23.11.2006	25-495-60730A	Flight Deck ECS Grilles - Introduction of Bolt A	X
EASA2006-0342		23.11.2006	25-495-60730A	Flight Deck ECS Grilles - Introduction of Bolt A	X
EASA2007-0058		1.3.2007	Read AD	Stabilisers - Elevator Drain Holes - Modification	Read AD
EASA2007-0075		3.4.2007	ISB53-191	Inspection of aft fuselage skin under APU shield	03042008/2
EASA2007-0076		4.4.2007	ISB29-047	Inspection of hydraulic accumulators	16052007
EASA2007-0270	R1	30.10.2007	ISB 57-033	Rear spar attachment fittings inspection	30.10.2007
EASA2007-0277		19.11.2007	ISB.53-194	Undercarriage main beam bolts inspection	4000 FC
EASA2007-0303		28.12.2007	SB 53-203	Forward and aft wing links inspection	4 yrs
EASA2007-0304		28.12.2007	SB 57-a071	Top skin under rib 0 joint strap inspection	Read AD
EASA2007-0305		3.1.2008	ISB 53-152 Rev3	LH nose lg well sidewall & retraction jack attachment	Read AD
EASA2007-0307		31.12.2007	ISB 53-200	Airbrake Upper Crossbeam Inspection	Read AD
EASA2008-0003		22.1.2008	ISB 53-175 R1	Wing links inspection	Read AD
EASA2008-0092	R1	27.5.2008	ISB 53-182	Frame flanges and door hinge bosses inspection	Read AD
EASA2008-0168		16.9.2008	ISB.57-070	Wing centre section inspection	Read AD
EASA2008-0180		14.10.2008	ISB.53.202R1	MLG door fairing panel grommets	(8000FC)
EASA2009-0014		4.2.2009	ISB.57-072	Fixed wing leading edge and front spar structure	Read AD
EASA2009-0020		19.2.2009	Read AD	Airworthiness limitations implementation	19.5.2009
EASA2009-0046		16.3.2009	ISB.53-213	Lug plate attachment joint inspection	16.2.2011
EASA2009-0070	R1	16.7.2010	ISB.53-167 2,3,4	External forward fuselage inspection / repair	Read AD
EASA2009-0205	R1	26.1.2010	SB.27-183-36246A	Aileron interconnect cable pulley guards installation	14.4.2010
EASA2010-0001-E		6.1.2010	ISB.A32-180R2	Nose landing gear inspection	6.1.2010
EASA2010-0201		19.10.2010	ISB.32-176	MLG shock absorber lower attachment pins	19102012/4
EASA2010-0202	R1	19.10.2010	ISB.32-182	Nose landing gear main fitting inspection / replacement	Read AD
EASA2011-0048		1.4.2011	BAe146 AMM ch.05	Airworthiness limitations	01072011
EASA2011-0065		21.4.2011	Sb.26-077-36250A	Inspection of baggage bay fire bottles wiring location	21072011
EASA2011-0097		8.6.2011	ISB.53-229R1	Inspection of NLG bay LH sidewall stiffeners	(12000 FC)
EASA2011-0099		9.6.2011	ISB.21-162R1	Inspection of front and rear discharger valves function	09062012/(
EASA2011-0216		22.11.2011	SB.25-549-65372A	Modification of galley stowage installation	22112013
EASA2011-0220		25.11.2011	SB 29-048-30676A	Hydraulic fluid containment system - installation	Read AD
G-2004-0004		26.2.2004	SB53-170	Pressure floor over MLG bay	1000L/3000
G-2004-0006		2.3.2004	SB34-371-70671A	Distance bearing indicator	02072004
G-2004-0031		4.1.2005	SB49-072-36244A	Insulation blankets on the APU exhaust	04072005
G-2005-0009		29.4.2004	ISB53-177	Inspection of center fuselage skin	29102005/
G-2005-0014		30.6.2005	ISB.27-177	Replacement of elevator bearings	31102006
G-2005-0015		29.7.2005	MM Rev. 82	Revised airworthiness limitations	29072005
G-2005-0017		29.7.2005	SB52-113R1	Inspection of MLG door hinges	X

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ	
G-2005-0018	29.7.2005	SB57-066R2	Inspection of wing flap	29072007	
G-2005-0019	29.7.2005	ISB53-182	Inspection of door frame	SB	
G-2005-0026	30.9.2005	SB25-459-36241A	Strengthening of the LH flying control duct	30062006	
<b>Boeing Company, The</b>					
<b>Boeing 757</b>					
AD1994-01-10	R2	28.1.2005	757-78-0025	Thrust reverser directional control valve	X
AD1996-19-17		7.10.1996	SB757-24A0079	Main battery shunt inspection	X
AD1997-02-19		4.3.1997	SB757-22A0052	Replacement of TMC	X
AD1997-09-06		12.5.1997	SB757-26A0040	Fire extinguishing system	X
AD1997-15-09		1.8.1997	D6-54446	APU battery ground	X
AD1997-18-04		17.9.1997	SB757-54A0020	Midspare fuse pins	X
AD1997-18-05		17.9.1997	SB757-54A0019	Midspar fuse pins	X
AD1998-03-10		19.2.1998	SB757-25-0183	Test of pilots' seats	X
AD1998-03-20		18.3.1998	SB757-24A0025	Chafing of wire bundles	X
AD1998-13-12	R1	28.12.1998	SB757-27A0128	Rudder pedal assemblies	X
AD1998-18-14		17.9.1998		Electrical wire bundles	X
AD1998-19-05		15.10.1998	SB757-57-0053R1	Wing center section front spar	X
AD1999-05-10		9.4.1999	ArkwinSB1211233	RAT deployment actuators	X
AD1999-10-14		17.6.1999	AS SB M4426	AlliedSignal ILS receiver	X
AD1999-17-20		24.9.1999	SB757-25-018R1	Emergency evacuation slide	X
AD1999-23-21		21.12.1999	SB757-76-0009	Reverse thrust switches	X
AD1999-24-11		4.1.2000	SB757-105-25-51	Slide/raft evacuation system	X
AD2000-04-18		4.4.2000	SB757-27A0127R1	Flap transmission	X
AD2000-07-13		16.5.2000	SB757-57A0054R1	Main landing gear fuse pins	X
AD2000-20-16		26.10.2000	SB757-25A0233	Cargo loader system	X
AD2000-26-05		1.2.2001	757-21A0084/0085	ECS duct assemblies	01022007
AD2001-02-09		5.3.2001	SB757-54-0031R2	Inspection of the tang	(3000L)
AD2001-09-01		6.6.2001	757-32A0135R1	MLG truck beam	X
AD2001-10-14		8.6.2001	757-35-0021/0022	Chemical oxygen generator	X
AD2001-11-07		16.7.2001	757-29A0048R3	Hydraulic shutoff valve	(6KK)/1607
AD2001-11-08		16.7.2001	SB757-31-0066R2	WEU/MAWEA power supply	X
AD2001-13-07		1.8.2001	757-28-0060R1	Fuel shutoff valve circuits	01022002
Ad2001-14-01		15.8.2001		Air-to-ground telephone sTC SA1727GL	15022003
AD2001-15-01		28.8.2001	SB757-25-0218	Deployment of escape slide	X
AD2001-20-11		15.11.2001	757-27A0086	Elevator free play check	3000H/4000
AD2001-23-14		31.12.2001	757-27A0133	Leading edge slats GRA	X
AD2002-02-04		19.3.2002	757-29-0058	Chafing between wires and wing spar	19092002
AD2002-10-02		20.6.2002	757-28-0057/0059	Simmonds FQIS extender bracket	20062006
AD2002-12-04		23.7.2002	757-27A0130R1	MLG & auto-speedbrake control system	23072007
AD2002-19-52		30.9.2002	757-28A0070	Center tank fuel pump	14102002

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
AD2002-21-14	29.11.2002	757-25-0214	Off-wing escape slide system	29112005
AD2002-24-02	7.1.2003	757-53A0080	Cargo doorway frames	X
AD2002-24-51	23.11.2002		Center tank fuel pump	27112002
AD2002-26-09	10.2.2003	757-25-0194	Overhead stowage bin st. 680	10022005
AD2003-07-13	20.5.2003	SB757-27A0125R2	Inboard trailing edge flaps drive system	AD
AD2003-14-08	18.8.2003		AFM: revision of donning oxygen masks	18112003
AD2003-18-05	16.10.2003	757-54-0034R1	Modification of nacelle struts and wing structur	X
AD2003-23-04	23.12.2003	757-25-0237R2	Modification of # 3 emergency exit doors	23122006
AD2003-23-05	24.12.2003		Titeflex Corporation hoses	24122005
AD2003-26-12	11.2.2004	757-23A0060R1	Short circuit in video distribution unit	11082005
AD2004-07-07	5.5.2004	SASB757-25-0181	Forward lavatory installation	05052006
AD2004-09-32	24.5.2004	SB757-53-0089	Inspection of L1 entry door cutout	(1400L)
AD2004-16-11	13.9.2004	SB757-29-0060	Hydraulic pump of the ram air turbine	13092007
AD2004-22-01	1.12.2004		Cargo restraint strap assembly	15122004
AD2004-23-06	21.12.2004	SB757-24-0089R1	Inspection of the W2000 wire bundle insulation	21062006
AD2004-23-12	21.12.2004	SB757-52-0077	# 1 left PAX door guide arm	21062006
AD2005-01-12	14.2.2005	SB757-27A0139	Trailing edge flap system ballscrews	14022009
AD2005-02-10	7.3.2005	ASB757-54A0045	Nacelle struts hydraulic line brackets (RR)	(3000H)
AD2005-03-02	9.3.2005	SB757-21-0088	Loosening of overhead ducts	09032011
AD2005-04-14	15.3.2005	SB757-54A0039R3	Joints of the mid-bulkhead and upper link fittin	15062005
AD2005-05-01	6.4.2005	SB757-33A0049	Lower anti-collision light connector	06042010
AD2005-06-02	20.4.2005	SB757-33-0050R2	Master dim and test system circuit	20042010
AD2005-07-08	5.5.2005	ASB757-57A0063	Control of leading edge slats	(18KK)
AD2005-12-11	20.7.2005	SB757-25-0255	Modification of the frecuency converter	20012007
AD2005-12-18	22.7.2005	SB757-27A0142R2	HSTA brake	30000H
AD2005-15-15	1.9.2005	SB757-54-0048	Upper link fwd fuse pins of engine struts	01092007
AD2005-17-09	27.9.2005	757-25-0226/28	Drip shields not adequately resistant to fire	AD
AD2005-18-09	12.10.2005	757-34A0258/0471	Replacement of Pegasus OPS & FIDO softwar	12042007
AD2005-18-18	14.10.2005	757-28A0073	Inspection of wire bundles (RR)	14102010
AD2005-20-40	17.11.2005	SB757-27-0150	Flap transmisssion assembly	17112010
AD2005-20-41	17.11.2005	SB757-29-0064	Brackets for hydraulic lines in nacelle struts (P	17112007
AD2005-22-07	30.11.2005	ASB757-24A0099	APU battery ground brackets, ground wires	31052007
AD2005-23-15	21.12.2006	Read AD	Assembly of control wheel damper	X
AD2006-07-21	16.5.2006	BSB757-54-0042	Cracking on midspar fittings on the nacelle str	Read AD
AD2006-07-23	16.5.2006	757-27-0148etc	Freeplay-induced vibration of the rudder	Read AD
AD2006-07-24	16.5.2006	SB757-24-0092/5	Replaceent of Px-x panels	16052008
AD2006-09-02	11.5.2006	ASB757-71A0085	Gap between the strut fitting and engine mount	11082006
AD2006-11-11	30.6.2006		Fatigue cracking of principal structural element	X
AD2006-12-06	12.7.2006	SA757-25-0238	Wire wrapping in galleys	12072012
AD2006-13-03	25.7.2006	Read AD	Fuel tank explosion	X

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
AD2006-13-17	13.7.2006	SA979NE-28SB28	Floor structure: STC SA979NE	12082006
AD2006-20-11	8.11.2006	BSASB757-53-0090	Fatigue cracking on fuselage skin lap splice	Read AD
AD2006-22-01	1.12.2006	Read AD	Escape slides failed	24 m
AD2006-26-13	12.2.2007	SB757-25-0223R1	Attendant shoulder harness brackets	12022010
AD2007-03-03	5.3.2007	Read AD	Inspection of certain power feeder wire bundle	X
AD2007-07-02	2.4.2007	Read AD	Chemical oxygen generators failed to activate	X
AD2007-10-12	27.6.2007	Read AD	Modification of flight deck door	Read AD
AD2007-16-12	13.9.2007	Read AD	IFE system electrics	13.9.2012
AD2007-19-07	28.11.2007	SB 757-53A0092	Skin pal joint inspections	Read AD
AD2007-23-08	20.12.2007	Read AD	Time delay relay inspection	20.12.2009
AD2007-26-02	22.1.2008	SB757-53A0093	Intercostal tee clips at PAX door cutout doorst	X
AD2008-01-01	6.7.2010	Read AD	Flight deck door feature replacement	5.8.2010
AD2008-02-14	28.2.2008	Read AD	Lighted pushbutton switches inspection	28.2.2008
AD2008-05-10	18.3.2008	ASB757-54A0047R3	Cracking in pylon	Read AD
AD2008-06-14	17.4.2008	SB 757-53-0077	Skin and stringer disbond inspection	Read AD
AD2008-08-08	19.5.2008	SB757-35-0028	Inspection of PAX oxygen masks	19052013
AD2008-08-12	19.5.2008	SB757-30-0021/22	Wing TAI system anchor tab	Katso SB
AD2008-09-07	8.5.2008		AFM limitations revision	8.6.2008
AD2008-10-11	12.6.2008		Fuel tank inspection	SEE AD
AD2008-11-07	3.7.2008	Read AD	Center tank fuel boost pump automatic shutoff	3.7.2011
AD2008-13-20	6.8.2008	Read AD	Thrust reverse aft hinge fitting inspection	6.8.2008
AD2008-13-20	6.8.2008	757-54-0049/0050	Aft hinge fittings of thrust reverse	X
Ad2008-22-08	17.12.2008	757-30-0024R1	Gray water composite drain mast	17122013
AD2008-23-09	15.12.2008	757-25-0295	Removal of insulation blanket AN-26	15121016
AD2008-25-08	15.1.2009	757-28-0095	Wiring of the fuel boost pump	15012014
AD2009-06-20	28.4.2009	ASB 757-28A0085	Fuel tank densitometer inspection	28.4.2014
AD2009-26-03	1.2.2010	757-24-0110R1	Modification of the static inverter	20130801
AD2010-06-17	3.5.2010	Read AD	Replacement of low-pressure oxygen hose	3.11.2011
AD2010-15-01	17.8.2010	SB757-30-0019R2	Inspection of flightdeck window electrical termi	See AD
AD2010-23-03	22.11.2010	SB757-28-0121	Test of EICAS	100H
AD2010-23-13	14.12.2010	SB757-57-0070	Lower fixed leading edge panel assy	14122015
AD2011-01-15	25.1.2011	SB757-53-0097	Cracking in the fuselage skin	SEE SB
AD2011-02-30	16.2.2011	SB757-32-0176R1	Material of nose wheel well springs	SEE SB
AD2011-05-04	31.3.2011	ASB757-57A0064R1	Sealing of fasteners in the main fuel tank	30122013
EASA2009-0101	11.6.2009	Read AD	Overspeed warning system modification	Read AD
<b>MD-11F</b>				
AD1996-12-09	29.7.1996	PTC SB24-1330	PTC Model 950 seat & footrest	X
AD1997-03-16	14.3.1997	MD11-28A082	Fuel pipe coupling	X
AD1999-25-14	18.1.2000	MD11-28A101	Tail tank fuel transfer pupms	X
AD2000-23-17	27.12.2000	MD11-36A030R03	Pneumatic sense line heater	X

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
AD2002-14-03	2.8.2002	MD11-57A067	Inboard flap outboard hinge	01092002
AD2002-14-04	23.8.2002	MD11-26-037	Firex bottle discharge cartridge	23112003
AD2002-14-06	23.8.2002	MD11-24-197	Overhead switch panel protective sleeving	28022004
AD2002-14-07	23.8.2002	MD11-24-036	Mod block tracks	23082003
Ad2002-14-08	23.8.2002	MD11-23A046R01	Avionics compartment wire bundles	23082003
AD2002-14-11	23.8.2002	MD11-24A138R01	Power receptacle ground wire attachments	23082003
AD2002-14-12	23.8.2002	MD11-28A058R01	Wing fuel control panel wiring	23022003
AD2002-14-14	23.8.2002	MD11-24A095R01	IDG wire harness support	23082003
AD2002-14-15	5.8.2002	MD11-25A227R01	Powered drive unit power wires	05022004
AD2002-23-18	31.12.2002	MD11-34-091	Radio altimeter receiver/transmitter	31032003
AD2003-03-15	R1 22.12.2003		Revision of flight manual	22032004
AD2003-04-16	27.5.2003	MD11-21A033R1	Chafed wires in avionics eq. compartment	27112004
AD2003-04-17	27.5.2003	MD11-24A179R2	Inspection of wiring/bundles	27112003
AD2003-08-08	27.5.2003	MD11-25A194R7	Chafing of electrical wire assemblies	27112003
AD2003-08-09	27.5.2003	Vrt. AD	Inspection of electrical wiring installations	08012006
AD2003-08-14	12.5.2003	MD11-28A120/121	Fuel boost/transfer pumps	27062003
AD2003-16-01	12.9.2003	MD11-33A071R1	O/H instrument lighting dimmer control	12032005
AD2003-17-07	R1 24.9.2003	DC9-26A029R1	Firex electrical circuits	24032005
AD2003-17-12	7.10.2003	MD11-24A137R1	Inspection of circuit breakers	07102005
AD2003-21-10	26.11.2003	mD11-24A174R3	Fwd cargo compartment terminal strips	26052005
AD2003-22-08	8.12.2003	MD11-55-023	Horizontal stabilizer barrel nut holes	08062005
AD2003-24-09	8.1.2004	MD11-24A157R1	#2 IDG parallel power feeder cables	08072004
AD2003-24-10	8.1.2004	MD11-27A080R1	Rudder pedal arm assembly	08072004
AD2003-25-10	27.1.2004	MD11-24A097R2	Wire connection stack up	X
AD2004-01-16	24.2.2004	MD11-24A173R2	Wire connection stackups	24082005
AD2004-01-19	24.2.2004	MD11-33A064	Bag rack lighting wire assy connectors	24022005
AD2004-02-06	5.3.2004	MD11-57A067	Replacement of flap bolts and washers	AD
AD2004-05-06	7.4.2004	MD11-25A262R1	Replacement of #1 PAX door view window	07102005
Ad2004-08-04	24.5.2004	MD11-28A110	Tail tank transfer pipe assy	700H
Ad2004-10-18	24.2.2004	MD11-24A196R1	Cabin & cargo vent fan wiring	24082004
AD2004-12-16	26.7.2004	MD11-24A181R1	Inspection of RCCBs of the AC cabin bus swit	700H
AD2004-14-10	13.8.2004	MD11-24A138R2	Replacement of ground support brackets	13082005
AD2004-19-05	27.10.2004	MD11-24A178R2	Avionics compartment terminal strips	2302006
AD2004-22-01	1.12.2004		Cargo restraint strap assembly	15122004
AD2004-22-17	14.12.2004	MD11-33A065R2	Cable assemblies of ODUs	14062006
AD2004-22-18	14.12.2004	MD11-22-026	Inspection of the auto throttle servo	14122007
AD2004-22-20	14.12.2004	MD11-24A175R1	Replacement of low base terminal boards	14062006
AD2005-02-06	7.3.2005	MD11-79A008	Replacement of oil pressure transmitter hose	07092006
AD2005-02-08	7.3.2005	MD11-28a119	Chafing of APU power feeder cables	07092006
AD2005-15-03	25.8.2005	MD11-52-044	Exterior emergency control handles	25022007

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
AD2005-15-12	30.8.2005	MD11-52-046R3	Forward passenger doors	28022007
AD2005-17-04	26.9.2005	MD11-26A060R1	Icing of the Firex discharge pipes (No. 2 engin	26032007
AD2005-20-15	10.11.2005	MD11-27A083	Inspection of the rudder pedal torque tube	10052006
AD2006-02-11	3.3.2006		Blocked drain holes of pitot tubes	1000h
AD2006-03-13	16.3.2006	MD11-57-076 etc	Corrosion and failure of flap hinge fitting studb	AD
AD2006-13-07	27.7.2006	MD11-25A233R1	Replacement of fwd crew rest area lamps	27012007
AD2006-19-03	17.10.2006	Alert bulletins	Fuel tank explosion	X
AD2007-01-02	14.2.2007	MD11-54A011R3	Power feeder cables for the IDG	Katso AD
AD2007-07-04	2.4.2007	Read AD	Fatigue cracking of principal structural element	Read AD
AD2007-10-12	27.6.2007	Read AD	Modification of flight deck door	Read AD
AD2007-11-16	5.6.2007	MD11-28-127	Inadequate bond of the internal fuel pump hou	X
AD2007-25-20	22.1.2008	SEE AD	Unwanted deployment of the thrust reverse sy	22012013
AD2008-06-21	R1 10.12.2009	Read AD	Additional maintenance inspections	Read AD
AD2008-11-14	3.7.2008	Read AD	Control cable freeze protection	3.7.2010
AD2008-17-16	2.10.2008	Read AD	Fuel boost pump modification	72/120 kk
AD2009-03-02	31.3.2009	Read AD	Wiring of AUX hydraulic pumps	Read AD
AD2010-09-12	8.6.2010	Read AD	Installation of fuel tank electrical bonding jump	8.6.2015
AD2010-11-12	6.6.2010	Read AD	Alternate fuel pump missing a case ground wir	18.2.2000
AD2010-16-03	9.9.2010		Airplane flight manual revision	13.9.2010
AD2010-20-14	5.11.2010	MD11-28-132R1	Fule tank explosion	05112015
AD2011-02-01	16.2.2011	MD11-28A124R1	Ignition sources inside fuel tanks	16022016
AD2011-11-05	6.7.2011	MD11-28A143	Fuel pump housing electrical connection	06052012
AD2011-25-06	17.1.2012	MD11-55-027	Replacement of anodized rub strips	17012017
<b>MD-90</b>				
AD1996-11-18	9.7.1996		Oxygen mask lanyards	X
AD1997-04-10	28.3.1997	MD80-22-122	Revision of flight manual	X
AD1998-18-17	8.10.1998	MD80-25A364	Tailcone emergency evacuation slide	X
AD1999-13-13	2.8.1999	DC9-27-355	Spoiler actuator piston	X
AD2000-08-18	13.6.2000	MD80-25A357	Deployment of evacuation slide	X
AD2000-11-01	30.6.2000	MD80-25-355R01	Insulation blankets	X
AD2000-15-15	23.8.2000	DC9-27A034	Horizontal stabilizer jackscrew	X
AD2000-15-17	12.9.2000	MD80-29-056/062	Hydraulic pipe assembly	X
AD2001-22-17	18.12.2001	MD80-29A067	Aux. hydraulic pump electric motors	18122002/5
AD2002-03-06	21.3.2002	MD80-27A359R1	Weight-on-wheels spoiler lockout	X
AD2002-04-01	28.3.2002	DC9-32-315/298	NLG upper lock link assembly	X
AD2002-10-03	20.6.2002	MD80-32-309R1	MLG shock strut pistons	X
AD2003-03-15	R1 22.12.2003		Revision of flight manual	22032004
AD2003-17-07	R1 24.9.2003	DC9-26A029R1	Firex electrical circuits	24032005
AD2004-22-01	1.12.2004		Cargo restraint strap assembly	15122004
AD2006-01-02	22.2.2006	DC9-32A240R1	Nose landing gear upper lock link	(4000L)

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ	
AD2006-07-11	5.5.2006	27-01-AMI15139A	Spoiler link aft attach fitting	05112007	
AD2006-10-14	21.6.2006	ReadAD	Cracks in the cargo door pan	ReadAD	
AD2007-17-19	2.10.2007	MD90-30-026 R1	Heater assembly inspection	18 months	
AD2009-13-08	3.8.2009	MD90-55A-012	Inspection of horizontal stabilizer	SEE SB	
AD2009-15-16	6.7.2010	TSB-88-52-045 E	Flight deck door modification	5.8.2010	
AD2010-05-04	1.4.2010	MD90-53A031	Cracking of overwing frames	01042015	
AD2010-16-11	22.9.2010	MD90-57-016 r2	MLG retract cylinder support fitting inspection	Read AD	
AD2010-21-16	18.11.2010	MD90-29A021R2	Modification of auxiliary hydraulic power syste	18052012	
AD2010-22-04	3.12.2010	MD90-54A003R2	Engine aft mounts fittings	SEE SB	
AD2011-01-11	9.2.2011	MD90-55A016R1	Inspection of the horizontal stabilizer	1680 FC	
AD2011-03-09	14.3.2011	MD90-74A002	Fire handle shutoff system wiring	X	
AD2011-06-12	26.4.2011	MD90-55A015	Horizontal stabilizer upper center skin panels	Read SB	
AD2011-12-12	22.7.2011	MD90-55A014	Inspection of vertical stabilizer	Read AD	
EASA2008-0197	12.11.2008	Read AD	AFM and pre-start check of the TWS	27.11.2008	
<b>Bombardier Inc.</b>					
<b>BD-100-1A10</b>					
CF-2005-12	R1	23.1.2009	Read AD	Failure of proximity-sensor electronic unit	6.2.2009
<b>BD-700 -1A10</b>					
CF-2008-31		9.10.2008	Read AD	Elevator PCU attachment bolt fracture	10FC/50FH
CF-2010-01		16.2.2010	Read AD	RAT non-conforming balance washer screws	18.2.2010
CF-2010-10		16.4.2010	Read AD	Relocating of hydraulic system lines	16.10.2012
CF-2010-14		1.6.2010		Passenger door tensator springs failure	1.7.2010
<b>CL-600-2B16</b>					
AD2005-11-04		27.5.2005	Raytheon 23-3727	Microphone jack. STC SA4900SW	01062005
CF-1995-02	R1	22.4.1999		Korkeusvakaimen trimmiaktuaattori	100599
CF-1997-16	R2	31.5.2001	SB604-53-006	FS409 bulkhead fatigue cracks	X
CF-1997-16	R1	8.10.1998	600-0679/601-501	Paineseinän tarkastus	600L
CF-1999-14		1.6.1999	SB600-0482/0671	Muutoksia laskutelinetilassa	15062000
CF-2000-30		10.10.2000	SB600-0684	Suojusten asentaminen	28022001
CF-2001-06		26.1.2001	SB A604-73-002	IDG cables chafed on cowl door	X
CF-2001-07		2.2.2001	AFM PSP604 1	Shift due to fuel migration	09022001
CF-2002-05	R1	28.6.2004	A604-27-011R1	Angle of attack transducer	300H
CF-2002-37		9.8.2002	A640-27-007	Flap vane brackets	(100L)
CF-2002-43		30.9.2002	A604-32-018R1	Main landing gear side-brace fitting shaft	28012003
CF-2003-20	R1	18.11.2011	604-32-014R2	Life limited landing gear parts	X
CF-2004-22		26.10.2004	A604-27-026	Angle of attack vanes	02112004/1
CF-2005-03		8.2.2005		Cold weather operations	22022005
CF-2005-06		18.4.2005		Corrosion prevention and control program	18042006
CF-2005-21	R1	25.7.2005	SB 604-27-013	Rudder balance spring assembly	25072006
CF-2008-12		25.2.2008	Read AD	Stick pusher capstan shaft failure	25.3.2008

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ	
CF-2008-16	R1	3.9.2008	Read AD	Enhancement of takeoff operational safety mar	Read AD
CF-2008-18		28.5.2008	Read AD	Wing anti-ice piccolo tubes	28.6.2008
CF-2009-18		19.5.2009	Read AD	ADG power feeder harness	19.7.2011
CF-2009-21	R1	26.5.2009	Read AD	NLG check	250h/6kk
CF-2009-24		8.6.2009	SB04-24-017	Air driven generator strut cracking	SEE AD
CF-2009-39		10.11.2009	Read AD	Hydraulic accumulator screw cap failure	50 H
CF-2009-49	R1	25.1.2010	Read AD	Wing anti-ice piccolo tube maintenance task	24.2.2010
CF-2009-50		25.1.2010	Read AD	ADG non-conforming balance washer screws	25.1.2010
CF-2010-25		24.8.2010	605-24-004	AC electrical load distribution	800 fh
CF-2011-08		19.5.2011	SB604-24-024	Air-driven generator electrical power feeder ca	19052017
CF-2011-11		17.6.2011	SB605-35-001R1	Oxygen cylinder and regulator assembly	31122011
CF-2011-25		13.8.2011	SB604-24-023	Air driven generator failure to power essential	13082014
CF-2011-33		31.8.2011	TLMC	Upper and lower engine support beam	30102011
CF-2011-37		10.11.2011	Read AD	LH engine fuel control input lever jamming	10112014
<b>CL-600-2B19</b>					
CF-2003-05	R2	10.7.2009	ASB A601R-21-053	Air supply ducts and bulkhead check valve ins	Read AD
CF-2004-01	R2	15.10.2009	TR 2A-47	Engine throttle control gearbox	14112009
CF-2008-09		18.2.2008	SB 601R-24-113	ADG internal wiring modification	18.2.2009
CF-2008-12		25.2.2008	Read AD	Stick pusher capstan shaft failure	25.3.2008
CF-2008-15	R1	20.8.2008	Read AD	Enhancement to takeoff operational safety mar	3.9.2008
CF-2008-18		28.5.2008	Read AD	Wing anti-ice piccolo tubes	28.6.2008
CF-2008-33	R1	9.2.2009	Read AD	Inboard flap actuator	11.3.2009
CF-2008-35R1		5.5.2010	SB 601R-27-154	Angle of attack transducer heating element de	Read AD
CF-2009-02	R1	13.1.2010	601R-11-088 RevB	Overwing emergency exit placards	19.2.2011
CF-2009-13		26.4.2009	Read AD	Flap actuator pinion gear non conformance	100 FC
CF-2009-13		26.3.2009	Read AD	Flap actuator pinion gear	100FC
CF-2009-19		19.5.2009	Read AD	NLG check	1600h/18kk
CF-2009-23		8.6.2009	IS67052110074	Passenger door corrosion	15000hAT/5
CF-2009-27		29.6.2009	SEE CF	Air driven generator strut cracking	X
CF-2009-31		8.7.2009	Read AD	Bulkhead check valves periodic discard task	6.9.2009
CF-2009-36		22.9.2009	CMR TR 2A-43	Stick pusher capstan shaft failure	22.10.2009
CF-2009-37		16.10.2009	SB601R-30-031A	Outboard wing low-heat detection switches	15112009
CF-2009-47		7.1.2010	SB 601R-24-128	ADG electrical harness assembly failure	6000FH/6yr
CF-2009-48		25.1.2010	Read AD	ADG non-conforming balance washer screws	25.1.2010
CF-2010-04		26.2.2010	A601R-27-157	AOA transducer resolver oil contamination	250h
CF-2010-12		26.5.2010	X	Wing LE thermal switches and wing anti-ice du	25.6.2010
CF-2010-24	R1	30.9.2011	Read AD	Hydraulic accumulators screw cap/end cap fail	17.9.2010
CF-2010-37		12.11.2010	SB601R-34-147RA	Air data computer water accumulator assembli	12082011
CF-2011-18		20.7.2011		Wire chafing in aft equipment bay	03092011
CF-2011-23		4.8.2011	SB601R-35-017RA	Damage to 3rd crewman oxygen system	X

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
CF-2011-26	13.8.2011	SB601R-24-130	Air driven generator failure to power essential	13082013
CF-2011-30	24.8.2011	TR 2B-2187	Forward face of rear pressure bulkhead	23102011
CF-2011-38	10.11.2011	SB601R-71-033	LH engine fuel control input lever jamming	10112014
CF-2011-39	14.11.2011	SB601R57-052	Failure of MLG side brace fitting shaft	Read AD
CF-2011-45	9.1.2012	SB601R-27-160	Horozontal stabilizer trim actuator att pins and	X
<b>Learjet 60()</b>				
AD1999-16-03	9.9.1999	SB23/24/25-30-3	Jäänestojärjestelmän sähköjohdot	X
AD2010-11-11	13.7.2010		Revision of maintenance manual tire servicing	27.7.2010
<b>Cessna Aircraft Company</b>				
<b>Cessna 750</b>				
AD2006-24-01	6.12.2006	Read AD	Chafing of the APU fuel tube assemblies	Read AD
AD2007-11-17	6.6.2007	Read AD	Mis-wired fire extinguishing bottles	X
AD2010-20-10	30.9.2010	SB750-27-62	Cracks in hinges and brackets inspection	Read AD
Ad2011-03-16	22.3.2011	SL750-24-08	Replacement of Pacific Scientific generators	22092011
<b>Dassault Aviation</b>				
<b>Falcon 2000</b>				
EASA2006-0003	5.1.2006	F2000-332/X-92	3rd crew member O2 box & feeder cables	04022006
EASA2006-0037	13.2.2006	F2000-331	Inspection of outboard leading edge slats	13092006
EASA2006-0113	24.5.2006	Read AD	Landing Gear components-surface protection	X
EASA2006-0115	24.5.2006	Read AD	Trailing edge flaps rotating rods-Inspection/mo	X
EASA2006-0148	21.6.2006	Read AD	Doors - Over Wing Emergency Exit - Inspectio	X
EASA2006-0276	16.9.2006	Zo.5053-30-001/2	Modification of wing anti-ice telescopic tubes	16042007
EASA2007-0016	26.1.2007	SB F2000-298	Modification of engine cowlings locking	26012008
EASA2008-0013	7.2.2008	Read AD	Third crew member control panel inspection	7.9.2008
EASA2008-0221	31.12.2008	Read AD	Continued airworthiness instructions revision	30.1.2009
EASA2009-0050	19.3.2009	Read AD	MLG shock absorber restrictor inspection	Read AD
EASA2011-0193	19.10.2011	F2000-358	Modification of wing fuel tanks	X
F-2002-413	7.8.2002	F2000-248	Engine nacelle firewalls	17032003
F-2003-084	R1 12.2.2003		Fire protection	05032003
F-2003-409(B)	29.10.2003	F2000-273	Hybridated GPIRS speed	X
F-2004-128	14.8.2004	F2000-299	Engine spherical bearing missing	X
F-2005-018	12.2.2005	SB F2000-301	Engine fail-safe fasteners	X
<b>Falcon 2000EX</b>				
EASA2006-0003	5.1.2006	F2000-332/X-92	3rd crew member O2 box & feeder cables	04022006
EASA2006-0037	13.2.2006	F2000-331	Inspection of outboard leading edge slats	13092006
EASA2006-0113	24.5.2006	Read AD	Landing Gear components-surface protection	X
EASA2006-0115	24.5.2006	Read AD	Trailing edge flaps rotating rods-Inspection/mo	X
EASA2006-0148	21.6.2006	Read AD	Doors - Over Wing Emergency Exit - Inspectio	X
EASA2006-0157	21.6.2006	Read AD	Navigation - Segregation of ADC / IRS wiring -	X
EASA2006-0356-E	1.12.2006	SB F2000EX-137	Fire Detection System Integrity - Inspection / R	X

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2007-0032		21.2.2007	F2000EX-100/-120	FLICK check of the software	40VRK
EASA2007-0073		5.4.2007	Read AD	Oxygen - Incompatible passenger mask boxes	X
EASA2007-0119		16.5.2007	F2000EX-138	Engine fire detection system - modification	X
EASA2007-0137		30.5.2007	F2000EX-116/-140	Wing anti-ice monitoring system	30112007
EASA2007-0290		10.12.2007	SB F2000EX-141	GCU wiring modification	10.1.2009
EASA2008-0143		14.8.2008	SB F2000EX-178	LH stringer 13 at fuselage frame 8	X
EASA2008-0221		31.12.2008	Read AD	Continued airworthiness instructions revision	30.1.2009
EASA2009-0050		19.3.2009	Read AD	MLG shock absorber restrictor inspection	Read AD
EASA2011-0193		19.10.2011	F2000-358	Modification of wing fuel tanks	X
F-2005-025		27.1.2005	SB-F2000EX-58/59	ASCB software	15022005
F-2005-140		26.7.2005	SB-F2000EX-80	Braking function anomalies (EASy)	X
<b>Falcon 7X</b>					
EASA2008-0221		31.12.2008	Read AD	Continued airworthiness instructions revision	30.1.2009
EASA2009-0208	R1	16.6.2010	Falcon 7X No100	Radio altimeter lock-up - operational procedure	Read AD
EASA2009-0254		15.12.2009	MM Ch.5.40	Revision of DC generator airworthiness limitati	14012010
EASA2010-0029	R1	25.10.2010	Read AD	Electrical wirings & hydraulic lines routing modi	15012011/6
EASA2010-0031		17.3.2010	SB F7X-065	Modification of weight-on-weight system	17062012
EASA2010-0032		17.3.2010	SB F7X-104	Modification of rear fuselage tank	17042012
EASA2010-0033		17.3.2010	24-50-25-720-801	Functional test of ram air turbine heater	650/1900F
EASA2010-0073		29.4.2010	7X no. 1 33	Transient voltage suppressor diodes	X
EASA2011-0008		18.1.2011	SB 7X-163	RAT transformer rectifier unit replacement	1.6.2013
EASA2011-0070		2.5.2011	F7X No. 174	Passenger oxygen line - inspection/modificatio	2.7.2011
EASA2011-0114	R2	7.7.2011	F7X-211/212 R2	Modification of horizontal stabilizer pitch contro	07072011
EASA2011-0241		2.1.2012	SB F7X-214	Horizontal stabilizer pitch trim	Read AD
<b>Falcon 900EX</b>					
EASA2006-0037		13.2.2006	F2000-331	Inspection of outboard leading edge slats	13092006
EASA2006-0113		24.5.2006	Read AD	Landing Gear components-surface protection	X
EASA2006-0149		21.6.2006	Read AD	Doors - Over Wing Emergency Exit - Inspectio	X
EASA2006-0157		21.6.2006	Read AD	Navigation - Segregation of ADC / IRS wiring -	X
EASA2006-0270		14.9.2006	F900EX-241/251	Inspection of electric power feeder	14042007
EASA2006-0330-E		26.10.2006		3rd Crew Member O2 Box & Feeder Cables - I	X
EASA2007-0032		21.2.2007	F2000EX-100/-120	FLICK check of the software	40VRK
EASA2007-0177		6.7.2007	Read AD	Operations in icing conditions- AFM revision a	Read AD
EASA2008-0013		7.2.2008	Read AD	Third crew member control panel inspection	7.9.2008
EASA2008-0221		31.12.2008	Read AD	Continued airworthiness instructions revision	30.1.2009
EASA2009-0126		2.7.2009	SB F900EX-347	Crew & passenger oxygen lines inspection	2.9.2009
EASA2011-0049		4.4.2011	SB F900-410	Replacement of fuel quantity sensor	04012012
EASA2011-0193		19.10.2011	F2000-358	Modification of wing fuel tanks	X
F-2003-084	R1	12.2.2003		Fire protection	05032003
F-2003-409(B)		29.10.2003	F2000-273	Hybridated GPIRS speed	X

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
F-2005-024		27.1.2005	SB-F900EX254	Indicating recording system - NIC	15022005
F-2005-066		7.5.2005	SB F900 EX-220	Missing rivets on central engine mast	X
<b>Mystere Falcon 20()</b>					
EASA2006-0156		21.6.2006	Read AD	Doors - Over Wing emergency Exit - Inspectio	24months
EASA2006-0156		21.6.2006	Read AD	Doors - Over Wing emergency Exit - Inspectio	24months
EASA2006-0185		20.7.2006	F20-768	Inspection of elevator bellcrank	X
EASA2007-0227		1.10.2007	SB F20-775	Replace wing anti-ice hoses	7 months
EASA2007-0262		30.10.2007	Read AD	Cockpit windows frames modification	16.7.2013
EASA2008-0123		16.7.2008	SB F20-766	Anti-ice pipe seal inspection	16.2.2009
EASA2008-0221		31.12.2008	Read AD	Continued airworthiness instructions revision	30.1.2009
EASA2009-0175		27.8.2009	TFE731-72-3750	LPT1 blades vibration monitoring	330FH/A-ch
F-1990-090-019	R2	2.2.2000		Syöpymätarkastus	12,5V
F-1996-092-021		8.5.1996	DMD11752	Siiven muotolevyjien tarkastus	7KK/330L
F-1998-114-023		6.4.1998		Lisäys hätätilanneohjeisiin	010598
F-1999-212-024		18.6.1999		Varauloskäynnin tarkastus	150899
F-1999-450		22.12.1999		Järjestelmien Y2K-sopivuus	01012000
F-1999-467-026		22.12.1999		Lentonopeuden rajoitus	15012000
F-2001-600-028		13.12.2001	WC53-20-07/-12	Ikkunan karmien tarkastus	X
<b>Embraer</b>					
<b>EMB-145()</b>					
CTA1999-02-01	R6	21.6.2004	SB145-27-0054R2	Aileron PCA rod ends	(25H/3VRK)
CTA2000-08-01	R3	6.8.2007	145-28-0013	Fuel pump electrics inspection	Read AD
CTA2001-04-02	R3	13.7.2007	Read AD	Installation of APU air inlet, exhaust silencer, p	Read AD
CTA2002-03-01	R3	6.12.2004	SB145-32-0068R1	Replacement of NLG wheel nut	X
CTA2002-09-01	R1	2.6.2004	SICMA147-25-020	Pilot/co-pilot seat tracks	X
CTA2002-10-03	R2	5.1.2005	SB145-76-0003	Inspection of the FADEC interface resistor mo	X
CTA2002-12-01	R1	20.7.2004	SB145-32-0066R1	Replacement of MLG strut bushings	X
CTA2002-12-03	R1	29.4.2009	Read AD	Elevator locking	21.12.2002
CTA2003-01-03	R1	26.7.2004	145-27-0098/0102	Electromechanical gust lock system	31072007
CTA2003-03-01	R1	14.10.2004	virt. CTA	Modification of the pitch trim system	03102004
CTA2003-07-01	R1	23.12.2003	145-80-0002/0006	Air turbine starter unit	X
CTA2004-01-02	R2	29.11.2004	SB145-30-0028R4	Modification of TAT sensor heating system	27042004
CTA2004-01-03		29.1.2004	SB145-29-0018	Replacement of hydraulic pump	31032004
CTA2004-01-05	R1	1.6.2004	SB145-33-0032	Tailboom strobe light electrical harness	05082006
CTA2004-01-07	R2	22.12.2005	SB145-27-A105R1	Inspection of the rudder II control rods	read AD
CTA2004-05-02		2.6.2004	SB145-25-0277	Inspection of passenger service units	02092004
CTA2004-05-03	R1	16.9.2005	SB145-53-0049	PAX seat tracks attaching screws	X/02062007
CTA2004-10-01		30.10.2004	SB145-26-0012	Inspection of engine fire handles	30042005
CTA2004-11-01		28.11.2004	SB145-27-0106	Replacement of horizontal stabilizer control uni	28052006
CTA2004-12-03	R1	14.1.2005	SB145-31-0042	Updating of the EICAS software	14072006

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
CTA2005-04-02		30.4.2005	SB145-32-0104	Modification of the steering system logic	30042008
CTA2005-04-03		1.6.2005	SB145-53-0057	Rework of the APU firewall	01062006
CTA2005-08-04	R1	27.7.2006	SB145-30-A050	Inspection of Pitot 3 relay K0057 and socket	27012007
CTA2005-09-02	R2	23.1.2007	Read AD	Wear of rudder-II attachment flange bushings	Read AD
CTA2005-10-04		17.11.2005	SB145-27-0108	Structural failure of aileron damper rod end	AD
CTA2005-10-05		17.11.2005	SB145-71-0008	Chafing of harness W407 at nacelle	X
CTA2006-02-03	R2	8.10.2006	SB145-28-0028	Fuel tank electrical bonding	X
CTA2006-03-01	R1	15.12.2006	ESB145-28-0025	Chafing of harnesses in the vicinity of fuel tank	X
CTA2006-05-01		23.5.2006	145-30-0043etc	Overheat of windshield temperature	X
CTA2006-06-02		28.6.2006	ESB145-28-0023..	Ignition source in the vicinity of fuel tanks	X
CTA2006-07-01		31.7.2006	145LEG-27-0023	Cable guard pins in the aileron control system	30042007
CTA2006-09-03		30.10.2006	Read AD	Engine anti-ice system valve failure	Read AD
CTA2007-05-01	R1	4.7.2007	Read AD	Cracks in the forward fuselage ritght hand side	Read AD
CTA2007-07-01		21.8.2007	145-00-0032	Operation with increased MTOW	60d
CTA2007-07-02		21.8.2007		Cracks in windshield fittings	Read AD
CTA2007-11-04	R1	21.12.2007	Read AD	Pitot and TAT current sensor relays and socke	Read AD
CTA2008-10-02		21.10.2008	SB 145-49-0034	APU mounting rods inspection	1500FH/6kk
CTA2009-01-01		8.1.2009	Read AD	LGEU replacement	8.1.2010
CTA2009-02-01		12.2.2009	Read AD	MLG trailing arm pin inspection	2500FH/24k
CTA2009-05-02		1.6.2009	Read AD	Maintenance program modification	90d
CTA2009-08-03		20.8.2009	Read AD	Fuel tank inspection	20.8.2009
EASA2007-0193-E		19.7.2007	AFM 145/1154r66	AFM Emergency and Abnormal Procedures A	19072007
EASA2007-0265		23.10.2007	Read AD	Fuel tank system AWL implementation	Read AD
<b>ERJ-170()</b>					
CTA E2007-03-01		16.3.2007	Read AD	Cargo door open during flight	Read AD
CTA2005-02-01	R1	24.4.2006	SB170-34-0001/3	Air data smart probes	24072006
CTA2005-03-01	R1	19.6.2006		Modification of A/P engaged ILS procedures	06042006
CTA2005-03-02	R1	11.8.2008	MRBR R2	Maintenance review board report	20052005
CTA2005-09-03	R2	25.2.2007	Read AD	Low pressure check valve replacement	Read AD
CTA2005-11-01		8.12.2005	ESB170-25-0024	Lavatory compartment doors mini-latches	X
CTA2005-12-05		19.1.2006	SB170-21-0014	Inspection of negative pressure relief valve	X
CTA2006-01-03		7.2.2006	SB170-26-0002	Installation of a debris strainer in the DMU inlet	X
CTA2006-03-02	R1	27.2.2007	Read AD	Temporary limitation in the AFM	next 1200 h
CTA2006-05-02		23.5.2006	AlertSB25A364	Emergency evacuation slide	X
CTA2006-05-04		14.6.2006	SB170-21-0017R1	Inspection of the smoke seal of aft avionics co	1200H
CTA2006-05-05	R1	25.2.2008	Read AD	Air data smart probes drain hole inspection	Read AD
CTA2006-05-06		14.6.2006	SB170-24-0026	Inspection of RAT deployment actuator	14092006
CTA2006-06-01		28.6.2006	ESB170-31-0013	Error in Primus EPIC digital platform	28.7.2006
CTA2006-06-03		7.7.2006		Loss of electrical bonding protection in fuel tan	X
CTA2006-11-02	R2	30.10.2007	Read AD	Check of the flight guidance control system	Read AD

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
CTA2007-01-02		15.1.2007	SB170-28-0011	Fuel quantity probes harnesses	X
CTA2007-02-01	R2	17.7.2009	Read AD	FWSOV additional operational check	600FH
CTA2007-03-01	R1	9.6.2008	see AD	Inspection of cargo doors	see AD
CTA2007-04-01	R1	21.12.2007	SB 170-29-0006	Replacement of hydraulic system clamps	Read AD
CTA2007-08-03		27.8.2007	SB 170-34-0019	Remove wiring of IRU	18 kk
CTA2007-11-01		12.12.2007	SB 170-21-0032	GVI of pressure equalization valves	500 FH
CTA2007-12-01		24.1.2008	SB 170-24-0041	Ram air turbine inspection	1300FH/6kk
CTA2008-01-03		3.3.2008	SB 170-25-0088	Evacuation slide inspection	600FH
CTA2008-03-01	R2	19.3.2009	SB170-73-0006	Replacement of engines FADEC software vers	X
CTA2008-09-01		30.9.2008	Read AD	Modification of electrical wiring and data bus	6000FH
CTA2008-10-04		10.11.2008	SB 170-54-0007	Pylon fastner inspection	5000FC
CTA2008-10-05		10.11.2008	SB 170-53-0057	RAT inspection	600FH
CTA2009-02-02		16.2.2009		Slat skew sensor operational check	1320FH
CTA2009-04-01		29.4.2009	Read AD	Maintenance program modification	28.7.2009
CTA2009-07-01		13.7.2009	SB170-57-0036	Wing stub rear box vapor barrier	13072011
CTA2009-11-01		30.11.2009	GSB4A030-25A379	Forward escape slides	31052010
CTA2010-01-01		31.1.2010	Read AD	Dispatch with EICAS message	10.2.2010
CTA2010-06-01	R1	25.8.2010	170-53-0082	Rear pressure bulkhead drill marks inspection	20000 FC
CTA2010-06-04		26.7.2010	170-24-0048	Ram air turbine inspection and identification / r	1200 FH / 6
CTA2010-07-02		31.7.2010	OB170-001/09R01	Revison of the Flight Manual	10082010
CTA2011-12-01		27.12.2011	SB 4A4030-25A402	Forward door escape slide maintenance interv	27062012
<b>ERJ-190()</b>					
CTA2006-03-03	R1	9.11.2007	Read AD	Temporary limitation to AFM	Read AD
CTA2006-05-08	R1	25.2.2008	Read AD	Air data smart probes drain hole inspection	Read AD
CTA2006-09-04	R1	5.2.2007	SB190-73-A007	Replacement of engine main fuel pump	30042007
CTA2006-11-01	R5	30.6.2010		Discard and replacement of LPCV	Read AD
CTA2006-11-03	R2	30.10.2007	Read AD	Check of the flight guidance control system	Read AD
CTA2007-02-02	R2	17.7.2009	Read AD	FWSOV additional operational check	600FH
CTA2007-03-02	R2	21.11.2008	Read AD	Cargo door open during flight	Read AD
CTA2007-04-02	R1	21.12.2007	SB 190-29-0003	Replacement of hydraulic system clamps	Read AD
CTA2007-08-04		27.8.2007	SB 190-34-0009	Remove wiring of IRU	18 kk
CTA2007-11-02		12.12.2007	SB 190-21-0019	GVI of pressure equalization valves	500 FH
CTA2007-12-02		24.1.2008	SB 190-24-0012	Ram air turbine inspection	1300FH/6kk
CTA2008-01-02		25.2.2008	SB 190-57-0005R1	Wing skin stringer modification	Read AD
CTA2008-01-04		3.3.2008	SB 190-25-0062	Evacuation slide inspection	600FH
CTA2008-09-02		30.9.2008	SB 190-54-0008	Inspection of fasteners of LH/RH pylons	5000FC
CTA2008-10-06		10.11.2008	SB 190-53-0027	RAT inspection	600FH
CTA2008-11-01		25.11.2008	190-32-A033	MLG locking stay bolts replacement	200FH
CTA2009-02-03		16.2.2009		Slat skew sensor operational check	1320FH
CTA2009-04-02		29.4.2009	Read AD	Maintenance program modification	28.7.2009

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
CTA2009-07-02		13.7.2009	SB190-57-0027	Wing stub rear box vapor barrier	13072011
CTA2009-08-02	R1	30.6.2010	Read AD	Replacement and modification of the forward e	Read AD
CTA2010-01-02	R1	30.6.2010		Prohibit dispatch if the message "recirc smk d	10.02.2010
CTA2010-06-02	R1	25.8.2010	190-53-0042	Rear pressure bulkhead drill marks inspection	20000 FC
CTA2010-06-05		26.7.2010	190-24-0019	Ram air turbine inspection and identification / r	1200 FH / 6
CTA2010-07-03		31.7.2010	OB170-001/09R1	Revsion of the Flight Manual	10082010
CTA2010-08-02		20.9.2010	Read AD	Replacement of the pylon shear pins	Read AD
CTA2010-08-03		20.9.2010		Revision of the airworthiness limitations sectio	19.11.2010
CTA2011-05-04		16.6.2011	MRB-1928	Airworthiness limitations inspectionsn updates	16092011
CTA2011-12-02		27.12.2011	Goodrich104003-2	Forward door escape slide maintenance interv	27062012

### **Hawker Beechcraft Corporation**

**Beechcraft Beechcraft**  
**MLL 200**

AD2004-22-02		1.12.2004	SB53-3486	Drain holes in the spoiler mixer bay panels	01122005
--------------	--	-----------	-----------	---	----------

### **RUAG Aerospace Services, GmbH**

**228-212**

D-2005-438		14.12.2005	AOT-228-24-028	Kurzschluss bei Kabelbaumhalter	read AD
D-2007-350	R1	30.1.2009	SB-228-270R1	Rudder and elevator surface protection de-bon	30.3.2009
D-2007-353		28.12.2007	SB-228-269	Replacement of rudder control cables	31032008
D-2008-149		5.5.2008	Read AD	NLG connection fatigue cracks	5.5.2008
D-2008-149		5.5.2008	SB-228-274	NLG cylinder and strut connection fatigue crac	Read AD
EASA2006-0352		27.11.2006	ASB228-265	Inspection of landing gear carbon brake assem	150H/3KK
EASA2007-0059		19.3.2007	DO228-119780-010	Honeywell ACAS II System - Modification	X
EASA2008-0217		24.12.2008	SB-228-275	Aileron actuator attachment riveting inspection	10 FH
EASA2009-0031		4.3.2009	ASB-228-279	Throttle box assembly inspection	Read AD
EASA2009-0062		27.3.2009	SB-228-276	Replacement of MLG stub axle	10.4.2009
EASA2009-0085		28.4.2009	SB-228-273	Fuselage frame 19	X
LTA1995-246		23.8.1995	SB228-215R1	Landing gear warning system	23111995
LTA1999-030	R3	29.5.2003	SB-228-235R1	Windshield wash system	31122003
LTA2001-045		26.1.2001	SB228-234	Horizontal stabilizer leading edge and ribs	100H
LTA2001-164		14.6.2001	SB228-236	Landing gear brake assembly	X
LTA2002-264		19.9.2002	AOT-228-21-024	Cockpit and cabin auxiliary heating wiring	31122002

### **SAAB AB, Aeronautics**

**340B**

EASA2006-0221		31.7.2006	340LKS9033	Fuel airworthiness limitations	31102006
EASA2006-0263		12.9.2006	SB340-32-133	MLG shock strut and axle adaptors	X
EASA2007-0168		29.6.2007	SB-340-57-031	Fuel access door - improved sealing	29.6.2013
EASA2007-0169		29.6.2007	SB-340-28-025	Wire separation of fuel quantity indication syst	29.6.2013
EASA2007-0170		29.6.2007	SB-340-28-024	Fuel quantity indication system wiring	29.6.2013
EASA2007-0248		21.9.2007	SB-340-28-026	Modification of fuel tank conduits wiring protect	21092013
EASA2008-0022		12.2.2008	AFM revisions	AFM revision for icng conditions	13032008

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2008-0054		19.3.2008	SB 340-32-136	Emergency extension valve functional check	19.9.2008
EASA2008-0069		25.4.2008	SB340-71-060	Inspection of frwd engine cowl door	X
EASA2008-0127	R1	22.7.2008	SB-340-28-027R1	Refuel/defuel panel illuminated placard inspect	22.10.2007
EASA2008-0146	R1	15.8.2008	SB340-29-023R1	Replacement of hydraulic accumulators	X
EASA2011-0003		31.1.2011	SB340-32-139	Replacement of MLG separation bolt harness	31012012
EASA2011-0078		19.5.2011	SB 340-27-100	Elevator pushrod assembly - identification/insp	Read AD
EASA2011-0219		25.11.2011	Read AD	Stall warning/identification system - replaceme	(25.11.2013
SAD1-022	E	5.12.1990	SB340-61-A42	Propeller hub inspection	X
SAD1-034		8.12.1989	SB340-54-026	Inspection of fittings in nacelles	X
SAD1-036		9.8.1991	SB340-55-022R1	Fatigue in stabilizer and wing	X
SAD1-038	A	29.6.1990	SB340-55-026R1	Yaw oscillations	X
SAD1-041		23.11.1990	SB340-34-068	Wire size in autopilot	X
SAD1-042		23.11.1990	SB340-71-035	FWD cowling door latch triggers	X
SAD1-044	A	27.12.1990	SB340-52-13R1	Toilet service door	X
SAD1-045		20.3.1991	SB340-25-181	Change of circuit breaker	X
SAD1-046		20.3.1991	SB340-28-013	Inner-wing fuel tanks	X
SAD1-047		20.3.1991	SB340-33-030	Emergency lighting	X
SAD1-048		23.4.1991	SB340-52-014	Passenger door handle mechanism	X
SAD1-049	A	5.7.1991	SB340-54-026	Nacelle lower drag strut	X
SAD1-050		1.7.1991	SB340MM	Electrical power to refuel panel lights	X
SAD1-051		18.12.1991	SB340-30-039	Stabilizer de-icing system	X
SAD1-052		21.1.1992	SB340-57-020	Fuel access door area	X
SAD1-054		12.8.1992	SB340-36-006	Sensor loops for bleed air	X
SAD1-055		4.9.1992	SB340-53-028	Installation of protective shield	X
SAD1-056		22.10.1992	SB340-28-016	Actuator on motor op. fuel valves	X
SAD1-057		23.10.1992	SB340-24-022	A.C. generator control relays	X
SAD1-060	A	15.11.1993	SB340-51-012	Elevator and ailerons coves	X
SAD1-061		15.11.1993	SB340-32-094R1	MLG retract actuator bracket	X
SAD1-064	R1	24.3.1995	SB340-61-032	Propeller brake-valve	X
SAD1-065		20.12.1994	SB340-53-047	Overwing emergency exit	X
SAD1-067		9.1.1995	SB340-76-034	Installation of beta stop mechanism	X
SAD1-070	R1	25.11.1996	SB340-76-032	Flight idle stop	X
SAD1-072		21.4.1995	SB340-57-027	Inspection of flap fittings	X
SAD1-075	R1	30.1.1997	SB340-32-105	Landing gear brakes	X
SAD1-079		24.11.1995		Nacelle fire extinguishers	X
SAD1-080		10.11.1995	SB340-26-016	Fire handle switches	X
SAD1-085	R1	22.1.1996	SB340-32-107	Anti-skid system	X
SAD1-103	R1	30.1.1997	SB340-33-040R1	Fluorescent lamp holders	X
SAD1-105		4.12.1996	SB340-53-032	Sealing of fire shield in APU	X
SAD1-106	R1	12.12.1996	SB340-25-235	Fire extinguishers	X

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
SAD1-107		6.2.1997	SB340-30-069	Ice & rain protection	X
SAD1-110	R2	7.12.1998	SB340-55-033R4	Horizontal stabilizer insp.	X
SAD1-113	R1	8.9.1998	SB340-33-047R1	Fluorescent lamps	X
SAD1-115	R1	17.11.1997	SB340-30-075	Wiper arm assembly	X
SAD1-116		9.6.1997	SB340-76-041	Flight idle stop override knob	X
SAD1-117	R1	9.6.1997	SB340-57-033	Replacement of flap support	X
SAD1-117	R1	2.3.1998	SB340-57-033R1	Wing flap support strap	X
SAD1-118	R1	5.5.2000	SB340-25-244R1	Baggage net placards	X
SAD1-119	R1	8.10.1998	SB340-30-073R1	Engine air intake	X
SAD1-120		24.11.1997	SB340-30-080	Ice and rain protection	X
SAD1-125		7.4.1998	SB340-32-115	Landing gear relay	X
SAD1-127		5.5.1998	SB340-32-114	Landing gear brakes	X
SAD1-128		29.5.1998	SB340-76-042	Control quadrant power cam	X
SAD1-133		20.10.1998	SB340-55-034	Horizontal stabilizer spar	X
SAD1-134		10.11.1998	SB340-32-116R1	Nose wheel	X
SAD1-135	R1	18.12.1998	SB340-71-057R1	Engine mounts inspection	X
SAD1-139	R1	1.10.1999	SB340-32-114	Brakes assemblies installation	X
SAD1-141		21.4.1999	SB340-53-061	Main frame insulation	X
SAD1-143		2.7.1999	SB340-76-043	Flight idle stop solenoid	X
SAD1-145		2.7.1999	SB340-20-009R2	Hydraulic power swivel bracket	X
SAD1-146		20.10.1999	SB340-57-036	MLG support assembly	X
SAD1-148		18.11.1999	SB340-76-041R1	Flight idle override knob	X
SAD1-149		10.12.1999	SB340-92-027	Electrical installations	X
SAD1-151		28.12.1999	SB340-26-023	Repalcement of smoke detector	X
SAD1-152		19.1.2000	SB340-57-035	Flap bushing/bolt	X
SAD1-153		19.1.2000	SB340-57-037	Flap fittings attachment lug	X
SAD1-155		28.2.2000	SB340-32-120	Landing gear extension	X
SAD1-156		28.2.2000	SB340-28-022	Refuel panel electrical connection	X
SAD1-161	R2	5.3.2001	SB340-51-020	Inspection of repainted aircraft	13022002
SAD1-167		1.10.2001	SB340-34-145	Change of main pitot static tubes	01102002
SAD1-169		20.11.2001	SB340-24-023R2	Removal of DC test switch	20112003
SAD1-170		17.12.2001	SB340-29-022	Life limitation on hydraulic hoses	31122003
SAD1-172		31.1.2002	SB340-61-038	Inspection of remote controlled circuit breakers	31072002
SAD1-173		4.3.2002	SB340-32-124	Landing gear retract actuator bracket bolt	04032003
SAD1-176		20.12.2002	SB340-54-043	Inspection of internal structiure of nacelles	X
SAD1-184		28.10.2002	SB340-26-029/30	Nacelle/pylons fire protection	28102003
SAD1-186		20.12.2002	SB340-32-127	Harness for the MLG separation bolt	20032003
SAD1-187		8.5.2003	SB340-57-042	Modification of the refuelling door	08052005
SAD1-189		1.4.2003	SB340-32-128	MLG - replacement of the harness for the sepa	01042004
SAD1-191		28.4.2003	SB340-32-130	Replacement of MLG assistor springs	28072003

<b>LKM</b>	<b>PVM</b>	<b>SB</b>	<b>OTSIKKO</b>	<b>TEHTÄVÄ</b>
SAD1-192	16.5.2003	SB340-71-059	Inspection of engine bottom mounts	X
SAD1-193	8.10.2003	SB340-30-088	Inspection of windshield wipers	08042004
SAD1-194	14.10.2003	SB340-51-025	Aileron and elevator trim tab fittings	14042004
SAD1-195	6.7.2004	SB340-32-131	Inspection of LG retract actuator bracket att. b	06012005
SAD1-196	R1 15.7.2004	SB340-24-026/35	DG starter generator brush inspection	X
SAD1-197	5.11.2004	SB340-24-026R2	DC generating system - CGU - undervoltage pr	05112007
SAD1-199	9.11.2005	SAAB340-32-132	Landing Gear - Replace Faulty Uplock Axles	09052006

**HELIKOPTERIT JA AUTOGIROT - H**

**Agusta, S.P.A. Costruzioni A.G.**

**Agusta-Bell 412()**

AD1989-08-05	8.5.1989		Pääroottorin vaihteiston tarkastus	(pt/50h)
AD1992-13-10	26.4.1993	SB412-91-54	Pyrstöroottoriakselin laakerin tarkastus ja vaiht	(JP)
AD1993-17-12	19.8.1994	BT412-42	Planeettahammaspyörän tarkastus	3100H
AD1994-18-09	29.9.1994	SB412-93-72RA	Pääroottorin vaihteiston hammaskehän käyntia	2500H
AD1997-07-06	16.4.1997	ASB412-92-57RA	Ohjauslevyn tuen tarkastus	(JP)
AD1997-11-04	10.6.1997	SB412-94-81	Osien hylkäysarvon laskeminen	X
AD1999-23-23	3.1.2000	ASB412-98-93	Pääroottorin napakappaleet	X
AD2000-18-09	28.8.2002	ASB412-00-100	Pyrstöpuomin kiinnitysalueen vahvike	100H
AD2001-09-11	30.5.2001	BT412-65/-96-89A	Pyrstöroottorin napakappale	25H
EASA2008-0142-E	1.8.2008	BT412-126	Rescue hoist cable life limitation	X
EASA2009-0185	3.9.2009	MBT 412-128	Left upper cap angle inspection	25FH
EASA2010-0171	31.8.2010	412-129	Wire strike protection system upper cable cutt	25 FH / 31.
EASA2010-0272-E	27.12.2010	206-248, 412-130	Pyrstöroottorin lapojen vaihto	X
EASA2011-0247	5.1.2012	BT 412-131	Collective lever - Inspection / replacement	Read AD
I-1995-025	20.12.1994	BT412-54A	Hydraulijärjestelmän putkien kiinnitys	010395
I-1997-194	14.7.1997	BT412-66	Pyrstöroottorin lapojen tarkastus.	300997
I-1998-186	17.6.1998	BT412-59RA	Pelastusvintturin tarkastus	JL/25H/12K
I-1999-179	3.1.2000	BT412-74	Pääroottorin napakappaleet	X
I-2000-331	20.7.2000	BT412-81	Sähköjohtojen asennus	X
I-2001-001	4.1.2001	BT412-83A	Vintturivaijerin leikkuri	150402001
I-2002-450	4.10.2002	BT412-89	Pelastusvintturin tarkastus	JL
I-2004-022	8.1.2004	BT412-95	Inspection of main hydraulic servo actuator wa	X
I-2005-139	22.9.2004	BT412-88Rev.A	Tail rotor blade tip block	BT
I-2005-430	21.10.2005	BTU412-111	External rescue hoist	read AD
I-2005-484	25.11.2005		Inspection of electrical cable cut...	X
I-2008-062	20.2.2008	ABT 412-124	Rescue hoist hook inspection	Read AD

**AW119MKII**

EASA2011-0095-E	25.5.2011	ABT 119-39 r A	Pilot and co-pilot control box assemblies - insp	5 FH / 21 d
-----------------	-----------	----------------	--	-------------

**AW139**

EASA2008-0108	19.6.2008	BT139-129	Replacement of cockpit door windows	19122008
EASA2008-0148	19.8.2008	BT139-126	Replacement of top cable cutter	X
EASA2009-0042	11.3.2009	BT 139-133	GCU replacement	11.9.2009
EASA2009-0183-C	12.8.2009	Read AD	Pelastusvintturin koukku	Read AD
EASA2009-0234-E	30.10.2009	ABT139-195	Inspection of tail boom	31102009
EASA2010-0237	R2 14.12.2010	SEE AD	Spectrolab Nightsun XP Searchlight	(JP)/301220
EASA2011-0081	23.5.2011	139-251	Tail rotor blades - inspection	Read AD
EASA2011-0205	27.10.2011		Tail fin assembly - inspection/replacement	Read AD

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2011-0207	3.11.2011	BT 139-269	Hydraulic systems - operational checks / repla	50 FH / 2 m
<b>Bell Helicopter Textron</b>				
<b>Bell 412()</b>				
AD1989-08-05	8.5.1989		Pääroottorin vaihteiston tarkastus	(pt/50h)
AD1992-13-10	26.4.1993	SB412-91-54	Pyrstöroottoriakselin laakerin tarkastus ja vaiht	(JP)
AD1993-17-12	19.8.1994	BT412-42	Planeettahammaspyörän tarkastus	3100H
AD1994-18-09	29.9.1994	SB412-93-72RA	Pääroottorin vaihteiston hammaskehän käyntia	2500H
AD1997-07-06	16.4.1997	ASB412-92-57RA	Ohjauslevyn tuen tarkastus	(JP)
AD1997-11-04	10.6.1997	SB412-94-81	Osien hylkäysarvon laskeminen	X
AD1999-23-23	3.1.2000	ASB412-98-93	Pääroottorin napakappaleet	X
AD2000-18-09	28.8.2002	ASB412-00-100	Pyrstöpuomin kiinnitysalueen vahvike	100H
AD2001-08-04	3.5.2001	41000470-67A-05	Aktuaattoreiden varmistuslevyjien tarkastus	X
AD2001-09-11	30.5.2001	BT412-65/-96-89A	Pyrstöroottorin napakappale	25H
AD2005-20-38	28.10.2005	AAI AA-05005RA	Emergency floatation nitrogen charging	29102005
AD2007-22-02	30.11.2007	ASB412-00-106	Tail rotor blade tip blocks	X
AD2008-10-03	21.5.2008		Check of tail rotor blades	JL/25H/30D
AD2009-05-09	31.3.2009	ASB412-08-128	Main rotor yoke	X
AD2010-10-16	8.6.2010	AA-10012	Low skid landing gear crosstube replacement	25 fh
AD2010-26-52	15.11.2011	ASB412-07-123RB	Replacement of tail rotor blades	13122010
AD2011-12-08	5.7.2011	SB412-09-136 RA	Inspection of tail rotor blades	X
<b>Eurocopter</b>				
<b>AS332()</b>				
EASA2006-0098	10.4.2006	ASB01.0054	Vintturin koukku	X
EASA2006-0306-E	11.10.2006	Alert SB 67.00.3	Rotor Flight Controls - Bolts - Check/Replacem	X
EASA2006-0340	R1 23.11.2006	ASB25.01.80R1	Seal of the jettisonable window	X
EASA2006-0361-E	2.12.2006	05.00.66	Main Gear Box (MGB) Main Casing, Check/Re	Read AD
EASA2007-0082-E	29.3.2007	Read AD	Fuel shut-off control lever - Check/reconditioni	Read AD
EASA2007-0099	25.4.2007	SB67.00.37	Inspection of rotors servo controls	20062007
EASA2007-0105	2.5.2007	ASB25.01.56	Hoist plate front attachment	X
EASA2007-0134	28.5.2007	Read AD	Engine-to-Main gearbox coupling saft flange b	X
EASA2008-0005	25.1.2008	ASB 52.00.33 R2	Plug doors modification	Read AD
EASA2008-0035-E	22.2.2008	ASB 05.00.76	Outer skin, butt strap & frame 5295 modificatio	Read AD
EASA2008-0075	6.5.2008	ASB01.00.72	Removal of seaat belt buckle plugs	06062008
EASA2008-0076	6.5.2008	ASB25.01.89	Relocation of ELT water-activated switch	06082008
EASA2008-0096E	28.5.2008	ASB25.01.97	Crash position indicator	X
EASA2008-0172-E	9.9.2008	AS332 N 62.00.73	Main rotor head check	9.9.2008
EASA2009-0003	R1 8.1.2009	Read AD	Main rotor blade de-icing system inspection	Read AD
EASA2009-0015	4.2.2009	Read AD	Hinged door upper and lower catches inspectio	220FH/6kk
EASA2009-0122	18.6.2009	Read AD	Kuormakoukun tarkastus	24.6.2009
EASA2009-0162	3.8.2009	ASB 25.02.11	Life-rafts inflation control system check	110FH/1kk

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2009-0164-E		31.7.2009	Read AD	Main rotor head spindle check	Read AD
EASA2009-0183-C		12.8.2009	Read AD	Pelastusvintturin koukku	Read AD
EASA2009-0227-E		24.10.2009	ASB 25.02.20	Modification of pilot and co-pilot seat rails	X
EASA2009-0263	R1	28.6.2010	Read AD	Emergency flotation gear inspection / repair / r	Read AD
EASA2009-0271	R1	22.1.2010	ASB25.02.08R2	Hydraulic hoist cable modification	Read AD
EASA2010-0014		9.2.2010	Read AD	Hoist operator's belt snap hook modification	3.7.2004
EASA2010-0043-E	R1	28.3.2010		Hydraulic pumps identification / replacement	15 fh
EASA2010-0117-E		18.6.2010	AS 332 67.00.40	Main rotor servocontrols end fitting ball joints i	Read AD
EASA2010-0234		23.11.2010	M.S.M	Airworthiness limitations	X
EASA2011-0180-E		16.9.2011	ASB No.01.00.80	Goodrich hois cable	X
EASA2011-0189-E		3.10.2011	ASB53.01.47R4	Replacement of IGB fairing	X
EASA2011-044-E		15.3.2011		Limitation of cabin sliding and plugging doors u	15032011
F-1983-094		19.4.1991	SB71-03	Pyrstöroottoriakselin palonsuojaus	x
F-1983-095	R2	21.2.1991	SB05.01R3	Lapavaimentimien kiinnityskorvakkeet	JL/8h
F-1986-121		9.10.1990	SB05.09	Pääroottorin navan holkkien tarkastus	jl/10h
F-1987-093		1.6.1990	SB55.01	Korkeusvakaimen kiinnityksen tarkastus	x
F-1987-103		7.11.1988	SB05.17	Lapavaimentimen laakerin vällys	50h/10h
F-1987-112		30.5.1991	SB05-15	Pyrstöroottorin lapojen tarkastus	600h
F-1988-099	R5	21.6.2000	SB05.00.22R4	Pääroottorin lapojen suojateipit	100/250/50
F-1990-136		21.9.1990	TD1/90	Pääroottorin vaihteiston tarkastus	x
F-1990-161	R2	12.3.1993	SB05.27R2	Välivaihteiston kuoren tarkastus	50H
F-1990-230	R4	28.2.2001	SB05.00.29R3	Pyrstöroottorin lapakulmien säätöjätjestelmän I	250H/18KK
F-1991-012	R3	4.12.1992	SB01.30 ISSUE2	Pyrstöroottorin napakappaleen tarkastus	JL/50H
F-1991-037		19.4.1991	SB23.07	Hätä lähettimen antennin korjaus	010891
F-1991-206		25.10.1991	SB05.35	Laskutelineen käyttimen muotolevy	T
F-1991-240	R3	18.6.1993	SB05-37	Pyrstöroottoriakselin tarkastus	JP/50H
F-1991-249	R1	6.10.1992	SB01.31R1	Sähkölaitekotelon suojapaneeli	x
F-1992-143		6.10.1992	SB24.20	Sähköjohtojen tukeminen	X
F-1992-146		26.8.1992		Välivaihteiston tarkastus	x
F-1993-106		30.6.1993	SB01-36R1	Saksinivelien laakereiden tarkastus	X
F-1993-131	R1	3.2.1995	SB01-41	Planeettapyörästäön tarkastus	X
F-1994-150		29.7.1994	SB01.38	Kuormakoukun muutostyö	X
F-1994-217		19.10.1994	SB01-39	Pyrstövalon varmistus	X
F-1995-029		15.2.1995	SB01-42	Pääroottorin lapojen jäänpoistojärjestelmä	X
F-1995-262	R1	8.5.1996	SB01.00.43R1	Pyrstöroottorin lapakulmien säätökara	(JP)
F-1996-074		26.4.1996	SB05.00.41	Lepatuslaakereiden kiinnikkeet	JP
F-1996-100		20.6.1996	SB01.00.44	Pääroottorin osien käyntiaikarajoitus	M
F-1996-263	R1	26.11.1997	SB01.00.47R1	Välivaihteiston kiinnitys	(JP)
F-1997-109	R1	22.5.1997	SB01.00.50	Ovien saranoiden tarkastus	X
F-1997-174	R1	23.2.2000	SB01.00.52	Pääroottorin silmukkapulttien laakerit	X

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
F-1997-202	18.9.1997	SB 01.00.49	Ylijännitesuojat	150198
F-1997-292	7.11.1997	SB05.00.43	Pääroottorin lapojen suojateipit	100H
F-1997-322	R2 28.2.2001	SB05.00.44R1	Pyrstöroottorin vaihteiston tarkastus	X
F-1998-155	R1 8.10.1999	SB05.00.45R1	Pyrstöroottorin jäänpoistojärjestelmä	110H/6KK
F-1998-254	4.8.1998	SB01.00.51	Sähkömoduulin tarkastus II	311298
F-1998-318	R5 3.5.2001	SB01.00.56R1	Polttoainesuodattimen ohivirtausventtiili	X
F-1998-487	R1 29.12.1998	SB01.00.58	Vintturin kiinnitys	X
F-1999-039	R2 31.12.1999	SB01.00.57R2	Korkeusvakaimen salon tarkastus	C
F-1999-257	R5 22.11.2001	ASB63.00.58	Kytkinakselin tarkastus	50H/550H
F-2000-003	2.2.2000	SB01.00.59	Pyrstöroottorin lavat	30042000
F-2000-486	R1 6.9.2001	ASB67.00.19	Polkimien säätövivut	1500H
F-2001-059	R1 15.8.2001	ASB77.00.11	Moottorin toiminta	25H
F-2002-257-080	R1 12.3.2005	ASB30.00.52	Electrical multi-purpose air intakes	X
F-2002-424-081	R3 9.4.2005	ASB05.00.58	Main gearbox - Bevel gear	150H
F-2002-452	R1 25.4.2003	ASB62.00.58/25	Dynaamisten komponenttien käyntiaikarajoitus	X
F-2002-508	R2 9.10.2004	SB01.00.67	Ferry tanks attachment	09102004
F-2002-551	R1 3.3.2004	ASB73.00.01	Engine fuel and control - fuel governor	X
F-2002-584	18.12.2002	ASB25.01.18	Vintturin sähköjohdotus	15032003
F-2003-101	11.3.2003	ASB67.00.25	Hydraulisäiliön tarkastus	01052003
F-2003-207	28.5.2003	ASB67.00.27	Pilot cyclic stick stops	28112003
F-2003-414	R1 3.3.2004	ASB05.00.59	Engine electronic control unit	JL
F-2004-031	R1 30.3.2005	ASB64.00.31	Tail rotor hub pitch control rod	10H
F-2004-170	R1 17.3.2005	ASB01.00.56	Vintturin koukku	26052005
F-2005-094	8.6.2005	ASB05.00.62	Engine fire extinguishers	AD
F-2005-100	2.7.2005	ASB32.00.18	Modification of the landing gear power supply	31052005
F-2005-118	6.6.2005	AT 53.01.49	Fiselage - Frame 5296 and rear MGB suspensi	X
F-2005-137	3.8.2005	ASB67.00.31	Tail servo-control	X
F-2005-146	17.8.2005	MT ASB095-49A11	Microturbo. Auxiliary power unit Saphir 20	31122005
F-2007-010	24.8.2007	ASB 01.00.73	Check hydraulic pump	15 FH
F-2007-010	24.8.2007	EASB 01.00.73	Check hydraulic pump	15FH
F-2007-027	7.12.2007	Read AD	TGB attachment fittings check	7.12.2007
F-91-248-046	8.1.1992		Polttoainesuodattimen kiinnittimen vaihto	500h
UF-2008-008	19.6.2008	Read AD	Main rotor blade de-icing system replacement	19.6.2008
<b>AS350()</b>				
CF-2005-16	18.7.2005	SB-ECL-113R1	Akun virtapiirin muutos (STC SH96-31)	01122005
EASA2006-0055	13.3.2006	ASB05.00.51/48	Servo-ohjaimien tarkastus	(10H)/0106
EASA2006-0098	10.4.2006	ASB01.0054	Vintturin koukku	X
EASA2006-0249	30.6.2006	ASB05.0041R2	Liukuovien rullat ja kiskot	100H
EASA2006-0363	21.12.2006	ASB67.00.39	Pyrstöroottorin ohjaustehostimen vipu	04122006
EASA2007-0139-E	22.5.2007	ASB53.00.37	Helikopterin tarkastus	(55H)/1805

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2007-0141-E		31.5.2007	ASB01.00.58R1	Servo-ohjainten tarkastus	23092007
EASA2007-0236		5.9.2007	ASB52.00.30R1	Liukuovien rullien tapit	110H
EASA2007-0289		30.11.2007	ASB67.00.16R2	Noususauvan korjaus	03122008
EASA2008-0044		3.3.2008	SB25.00.70	Takapenkin muutos	X
EASA2008-0214-E		9.12.2008	ASB 01.00.59	Hätäkelukkeiden tarkastus	10.12.2008
EASA2009-0011		30.1.2009	Read AD	Lentokelpoisuusrajoitusten päivitys	11.2.2009
EASA2009-0019		12.2.2009	ASB 05.00.58	Noususauvan lukitusnastan tarkastus	17.2.2009
EASA2009-0027		19.2.2009	Read AD	Käynnistingeneraattorin tarkastus	110FH/4.6.
EASA2009-0030		16.2.2009	ASB 55.00.16	Sivuvakaimen kiinnitys	31.3.2009
EASA2009-0039		23.2.2009	ASB05.00.40R3	Pyrstöroottorin lapojen tarkastus	JP/10H
EASA2009-0122		18.6.2009	Read AD	Kuormakoukun tarkastus	24.6.2009
EASA2009-0183-C		12.8.2009	Read AD	Pelastusvintturin koukku	Read AD
EASA2009-0277	R1	18.2.2009	863520-26-001	Halonisammuttimen vaihto	20100706
EASA2010-0006		8.1.2010	ASB 05.00.60	Pyrstöroottorin säätövarsien tarkastus	30FH
EASA2011-0033		8.3.2011	ASB No. 29.00.13	Eurocopter. Hydrauliservon letkujen suojien as	15.4.2011
EASA2011-0038-E		15.3.2011	ASB05.00.62R2	Pyrstöroottorin vaihteiston ohjausvipu	Read AD
EASA2011-0072		4.5.2011	Read AD	Hätäkelukejärjestelmän kiinnityskorvakkeet	Read AD
EASA2011-0104		10.6.2011	ASB65.00.46	Inspection of tail gear box casting assembly	Read AD
EASA2011-0164		14.9.2011	AS350-05.00.64	Inspection of tail rotor control stop screws	110FH
EASA2011-0244-E		22.12.2011	Read AD	Position strobe light - inspection / deactivation	Read AD
F-1997-147-072	R1	23.1.2002	ASB01.0046	Pyrstöpuomin kiinnityspultit	15022002
F-1999-085-076	R3	1.3.2002	ASB05.00.29	Pyrstöroottorin ohjauslevyn laakeri	50H/6KK
F-2000-222-079	R1	10.9.2004	SB05.0033R1	Pyrstöroottorin ohjaus	(JP)
F-2000-268-078		11.7.2000	SB79.00.11R1	Huohotinputken suojaus	31122000
F-2000-302		20.7.2000	ST28.07/09/26/	Siirtolentosäiliön maadotus	X
F-2001-074-081		28.2.2001	AT01.00.48	Pyrstöroottorin ohjauslevyn laakeri	300H/1200
F-2001-557-086	R3	13.5.2002	AT05.0038R2	Starflex-navan tarkastus	JL
F-2001-580-085	R2	10.12.2004	ASB05.00.37R1	Pyrstöroottorin servo-ohjaus	X
F-2002-281-091	R1	19.3.2004	ASB34.00.13	HSI-yksikön tarkastus	01082002
F-2002-452	R1	25.4.2003	ASB62.00.58/25	Dynaamisten komponenttien käyntiaikarajoitus	X
F-2002-537-094		1.11.2002	ASB53.00.31	Päävaihteiston kuomujen tiivisteet	31.5.2003
F-2003-002	R1	18.2.2004	ASB67.00.24	Ohjaussauvan tarkastus	31032004
F-2003-099		11.3.2003	ASB01.00.52	Servo-ohjaimen vaihto	X
F-2003-260	R1	10.6.2004	ASB24.00.10	Akun tarkastus	10062004
F-2003-322	R1	3.6.2004	67.00.25R1	Ohjainjärjestelmän rajoitinruuvit	X
F-2003-406(A)		5.11.2003	ASB67.00.27	Noususauvan lukko	X
F-2004-033		19.3.2004	ASB28.00.16	Polttoainesäiliön vedenpoistovipu	26092004
F-2004-035		19.3.2004	ASB05.0043	Runkokaaren tarkastus ja korjaus	Lkm
F-2004-055		23.4.2004	ASB05.00.45	Hydraulinesteen vaihto kylmässä säässä	X
F-2004-089		23.6.2004	ASB29.00.07	Hydraulijärjestelmä	31122004

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ	
F-2004-170	R1	17.3.2005	ASB01.00.56	Vintturin koukku	26052005
F-2004-174		10.11.2004		Hydraulijärjestelmän epäkuntoon joutuminen	20122004
F-2004-178		10.11.2004	ASB64.00.05	Pyrstöroottorin lavan laippa	20022005
F-2005-042		17.3.2005	ASB67.0026R1	Pyrstöroottorihjauksen korjaus	31122005
F-98-173-073		17.9.1998	SB05.00.08R5	Pyrstöroottorin laakereiden tarkastus	100H/400H/
F-98-511-074		9.2.1999	SB01.00.47	Ylijännitesuojat	010699
<b>AS365()</b>					
EASA2006-0098		10.4.2006	ASB01.0054	Vintturin koukku	X
EASA2006-0099		5.5.2006	ASB05.0049	Tail rotor blade check	10H/15H
EASA2006-0101		5.5.2006	ASB05.00.45R1	Check of main gearbox base plate	X
EASA2006-0213		28.7.2006	FM Suppl. 18	Optional ski installation	28072006
EASA2006-0362-E		2.12.2006	Read AD	Main Rotor Head Frequency Adapters - Modifi	Read AD
EASA2006-0368	R1	16.12.2010	ASB62.00.23R1	Check of rotor mast nut	X
EASA2006-0368-E		8.12.2006	Read AD	Rotor Mast Nut - Check / Replacement	Read AD
EASA2007-0099		25.4.2007	SB67.00.37	Inspection of rotors servo controls	20062007
EASA2007-0129		24.5.2007	ASB05.00.37R2	MGB suspension diagonal crossmember	50H/250J
EASA2007-0220		27.8.2007	ASB 01.00.59	Tail rotor pitch control replacement	31.12.2007
EASA2007-0259-E		2.10.2007	Read AD	Upper fin fitting inspection	Read AD
EASA2007-0288-E		19.11.2007	Read AD	MGB planet gear carrier inspection	19.11.2007
EASA2008-0165		11.9.2008	Read AD	Starflex star arm ends check	Read AD
EASA2008-0204-E		8.12.2008	ASB 01.00.60	VNE and R/D limitations	7.6.2008
EASA2009-0122		18.6.2009	Read AD	Kuormakoukun tarkastus	24.6.2009
EASA2009-0183-C		12.8.2009	Read AD	Pelastusvintturin koukku	Read AD
EASA2010-0014		9.2.2010	Read AD	Hoist operator's belt snap hook modification	3.7.2004
EASA2010-0100	R1	18.8.2010	ASB No.34.00.31R	Vertical gyro unit data output - operational limit	Read AD
EASA2011-0127		15.7.2011	ASB63.00.17	Inspection of main gearbox casing	X
EASA2011-0144		9.8.2011	ASB 05.00.60R1	Tail rotor hub inspectio	Read AD
EASA2011-0145		2.8.2011	Read AD	TGB inspection & tail rotor inspection	Read AD
EASA2011-0154		5.9.2011	ASB 67.00.10R1	Adjustment of collective pitch lever restraining	X
EASA2011-0190		14.10.2011	ASB53.00.50R1	Modification of fuselage draining system	X
F-2000-302		20.7.2000	ST28.07/09/26/	Siirtolentosäiliön maadotus	X
F-2002-452	R1	25.4.2003	ASB62.00.58/25	Dynaamisten komponenttien käyntiaikarajoitus	X
F-2003-322	R1	3.6.2004	67.00.25R1	Ohjainjärjestelmän rajoitinruuvit	X
F-2006-042		19.7.2006	ASB29.00.08	Check of flexible hydraulic pipes	19072009
<b>BO105()</b>					
EASA2008-0206		9.12.2008	Read AD	Balance weights and control lever inspection	2kk/100FH
EASA2010-0049		2.4.2010	Read AD	Cyclic-stick locking device modification	Raed AD
EASA2010-0128		7.7.2010	CEB A-1400 r3	Power turbine speed operational limitation	7.8.2010
EASA2010-0153		10.8.2010	BO105-10-121R1	Main rotor blades with bolted lead inner weight	Read AD
EASA2010-0216-E		22.10.2010	Read AD	Main rotor blade erosion protective shell inspe	10FH/4FC/4

LKM		PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2011-0091		1.6.2011	ASB BO105-10-125	Main gear box - inspection	Read AD
LTA1999-289	R3	9.4.2001	BO105-10-113R3	Vääntö- ja jännityspakkojen vaihto	10V/25000
LTA1999-300	R3	9.4.2001	BO105-10-114R2	Vääntö- ja jännityspakkojen vaihto	SB
LTA2001-281		24.9.2001	BO105-10-115	Jännitysliuskojen kalenteriaika	10V
LTA91-204		16.1.1992	BO105-60-105	Putkien tarkastus	x
LTA92-273		1.6.1992	ASB105-30-104	Vaihteistojen tarkastus	x
LTA97-275		9.10.1997	ASB-BO105-10-110	Pääroottorin maston tarkastus	100H
<b>EC120()</b>					
EASA2006-0253		30.8.2006	ASB76A006R1	Kiertokahvan tarkastus	X
EASA2007-0211		8.8.2007	ASB05A006	Kitkarenkaan tarkastus	110H
EASA2007-0311		7.1.2008	ASB25A023/025	Istuimien korjaus	04042008
EASA2008-0177-E		23.9.2008	EC120 ASB 04A007	Hätäkelukkeiden tarkastus	19.9.2008
EASA2008-0185		10.10.2008	ASB 76A005	Kiertokahvan tarkastus	22.10.2008
EASA2009-0122		18.6.2009	Read AD	Kuormakoukun tarkastus	24.6.2009
EASA2009-0277	R1	18.2.2009	863520-26-001	Halonisammuttimen vaihto	20100706
EASA2010-0026-E		22.2.2010	EASB120 05A012	Pääroottorin navan tarkastus	15 FH
EASA2011-0185		7.10.2011	ASB05A011,25A026	Inspection of emergency floatation gear	Read AD
F-1999-151-001	R1	6.9.2001	ASB04A001	Pyrstöroottorin vaihteiston tarkastus	X
F-2000-058-003	R1	6.9.2001	ASB04A002	Lentokelvottomat osat	01102001
F-2001-386-007	R1	6.9.2001	ASB67A005	Jalkapolkimien suojaus	28022002
F-2002-282-009	R1	19.3.2004	ASB34A006	HSL-yksikön tarkastus	01082002
F-2002-371-010	R1	23.4.2004	ASB67A008	Ohjaussauvan johtopunos	08052005
F-2002-606	R1	4.3.2005	ASB67A009	Nostosauvan kitkalukko	X
F-2003-322	R1	3.6.2004	67.00.25R1	Ohjainjärjestelmän rajoitinruuvit	X
F-2003-325	R1	3.6.2004	SB71.003/005	Voimansiirtoputken tarkastus	(JP/5H)
F-2003-465	R2	18.7.2005	ASB65A004	Pyrstöroottoriakselin vaimennin	X
F-2005-086		14.6.2005	SB67A014	Noususauvan liitoskappale	30042006
F-2005-175		25.10.2005	ASB67A011R1	Ohjaussauvan painelaatat	31122005
F-2006-040		2.2.2006	AT04A006	Painelaakereiden käyttökielto	27012006
<b>EC135()</b>					
D-2005-414		1.12.2005	EC135-32A-010	Hätäkelukeasennuksen muutos	22.12.2005
EASA2006-0318	R1	15.11.2006	EC135-67A-012	Pyrstöroottorijärjestelmän laakeri	30102006
EASA2007-0021		2.2.2007	EC135-53A-017	Sähköjohtojen tarkastus	28022007
EASA2007-0165		21.6.2007	EC135-24A-013R1	Sähköjohtojen asennuksen muutos	31122007
EASA2008-0064		18.4.2008	EC135-67A-017R2	Tail rotor control rod & pivot	X
EASA2008-0113		24.6.2008	EC135-67A-015	Modification of cyclic stick locking device	31072008
EASA2008-0175-E		18.9.2008	EC135-63A-013	Main transmission mast bearing retainer bolts i	Read AD
EASA2008-0175-E		18.9.2008	EC135-63A-013	Main transmission mast bearing retainer bolts i	Read AD
EASA2009-0106	R1	10.11.2011	EC135-63A-012 r4	Main gear box oil sampling & analysis program	Read AD
EASA2009-0183-C		12.8.2009	Read AD	Pelastusvintturin koukku	Read AD

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
EASA2009-0207	14.10.2009	ECD MSM ch4r10	Airworthiness limitations amendment	13.11.2009
EASA2009-0272	22.12.2009	EC135-62A-021	Lentoa edeltävä tarkastus	X
EASA2010-0058	13.4.2010	Read AD	Tail rotor, cyclic and collective control levers in	13.4.2011
EASA2010-0154	27.8.2010	Read AD	External hoist system visual check / replaceme	Read AD
EASA2010-0207	R1 25.5.2011	Read AD	Instrument control panel - flight limitation / mod	Read AD
EASA2010-0213	28.10.2010	EC135-63A-017	Modification of main transmission housing upp	28012011
EASA2010-0227	17.11.2010	EC135-67A-017R3	Inspection of tail rotor conrtol rod & ball pivot	See AD
EASA2010-0237	R2 14.12.2010	SEE AD	Spectrolab Nightsun XP Searchlight	(JP)/301220
EASA2010-0254	6.12.2010	Read AD	Tail boom pre-flight check	BNF/25FH
EASA2011-0111	R1 29.9.2011	Read AD	Mechanical air conditioning system - inspectio	25 FH / 14
EASA2011-0168	16.9.2011	EC135-33A-009R2	Modification of instrument lighting brightness f	16032013
EASA2011-0172	21.9.2011	EC135-26A-003R1	Replacement of fire extinguishing injection tub	Read AD
LTA1999-185	R4 24.9.2001	EC135-62A-004R3	Pääroottorin masto	15H/100H
LTA1999-199	R3 8.10.1999	EC135-53A-010R2	Pyrstöroottoriakselin laakerikorvakkeen laippa	071199/50H
LTA1999-264	12.7.1999	EC135-62A-005	Lapavaimentimien pulttien tarkastus	(15H)
LTA2001-107	R2 28.8.2002	EC135-63A-002R2	Vääntösauvojen tarkastus	X
LTA2001-306	R3 29.10.2001	EC135-31A-002R2	Näytön vaihto	31032002

**MOOTTORIT**

**CFM International**

**CFM56-()**

AD2009-11-02		23.6.2009		HPC spool cracking	8900cy/110
EASA2007-0221		27.8.2007	SB 72-0620	LP Turbine rear frame life reduction	Read AD
EASA2009-0088	R1	8.5.2009	S/B 72-0722	HPC inspection	Read AD
EASA2009-0110		21.5.2009	SB72-0620R2	Inspection of LPT rear frame	20062009
EASA2009-0154-E		17.7.2009	73-0238/0239	Inspection of hydromechanical unit (HMU)	18072009
EASA2010-0212		1.11.2010	S/B 72-0777	Replacement of fan blade	X
F-1998-003	R3	12.12.2001	SB72-229R1	Life limit - LP turbine casing	X
F-1998-334		12.8.1998	SB72-541	Life limit - HPT seal	X
F-1998-427	R1	30.12.1998	SB73-136R1/056R1	Fuel filter cover attachment	X
F-2001-177		16.5.2001	80-006/009/014R2	Overtorque of magnetic plug	X
F-2001-240		13.6.2001	SEE CN	Bearing no. 4 replacement	(50H)/3112
F-2002-470		18.9.2002	SB72-0328	2nd and 3rd stage LP turbine nozzle segments	X
F-2003-001	R2	18.6.2005	SB77-0020/0008R3	EGT harnesses and couplings	X
F-2003-456	R2	9.10.2004	SB80-0011R1	Starter	31122009
F-2004-095		23.6.2004	SB73-0126R4	Replacement of main fuel pumps	01012007

**General Electric Co.**

**CF34-10E()**

AD2007-12-15		19.7.2007	SB73-0013	Exchange of main fuel pump	31072007
AD2008-05-01		3.4.2008	Read AD	FMU overspeed solenoids test	Read AD
AD2011-18-02		26.9.2011	SB 72-0186	Fan rotor spinner support	X

**CF34-3B()**

AD2001-19-02		9.10.2001	SB79-A0014/0015	Inspection and cleaning of of B-sump screens	100H/500H
AD2002-05-02		12.4.2002		Mandatory inspection requirement	X
AD2003-05-10	R1	18.11.2003	SB79-A0014/15R3	B-sump scavenge screens	(100H/200H
AD2004-26-02		26.1.2005		Removal of HPC forward spools	X
AD2006-04-12		30.3.2006	SB72-A0178/A0152	Inspection of stage 5 and 6 LPT disks	AD
AD2006-05-04		7.4.2006	CF34-BJ72-A...etc	Rupture of fan disk due to cracks	X
AD2007-04-51		12.3.2007	Read AD	Inspection of fan disk	Read AD
AD2007-07-07	R1	12.9.2007	Read AD	Fan disk failure during flight	Read AD
AD2009-07-12		7.5.2009	Read AD	4-step seal modification	Read AD
AD2009-26-09		11.2.2010	Read AD	Uncontained fan disk failure	Read AD
AD2010-01-04		25.1.2010	Read AD	Fan blade rub strip inspection	Read AD

**CF34-8E()**

AD2008-05-01		3.4.2008	Read AD	FMU overspeed solenoids test	Read AD
AD2009-24-06		28.12.2009	SB73-A0020	Removal of FADEC softa 8Ev5.40	X

**CF6-80**

AD1990-26-01		16.12.1987	SB73-053	N/A	X
--------------	--	------------	----------	-----	---

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
AD1993-14-18	4.10.1993	SB72-596/565R1	N/A	X
AD1994-06-03	29.4.1994	SB72-614	N/A	X
AD1994-20-06	27.12.1994	SB72-097/648/628	N/A	X
AD1995-10-11	31.5.1995	SB78-1002	CDU brake holding feature	X
AD1995-23-03	6.12.1995	SB72-1108	HPCR stage 3 - 9 spools	X
AD1996-16-07	28.8.1996	SB72-835R1	RH mount link	X
AD1997-22-14	17.11.1997	SB72-A906	HPCR spool	X
AD1998-22-06	23.11.1998	SB72-A478R4	Stage 1 fan disk inspection	X
AD2000-03-04	10.4.2000	SB72-958	Fan mid shaft failure	X
AD2000-04-14	1.5.2000	SB73-A224R2	Fuel tube flange seating	X
AD2000-12-08	28.8.2000	SB72-A0964	Engine mount link failure	X
AD2002-25-08	23.1.2003	katso AD	High pressure compressor rotor stage 3-9 spo	katso AD
AD2003-02-07	3.3.2003		Replacement of stage 2,3 and 4 LPT shrouds	31072010
AD2004-04-07	12.3.2004	SB72-1089/1024	Stage 1 HPT rotor discs	X
AD2004-07-13	6.5.2004		Replacement of HPT stage 1 disk	10720CSN
AD2004-22-07	3.4.2005	SB72-0952R6	High pressure turbine stage 2 nozzle guide va	AD
AD2005-17-05	27.9.2005	S/B 72-1052	HPCR stage 11-14 spool shaft	AD
AD2006-06-08	25.4.2006	Read AD	Released thrust reverser hardware	X
AD2007-05-14	9.4.2007	Read AD	Cracks in a forward engine mount platform	Read AD
AD2007-11-20	10.7.2007	Read AD	External engine fuel leakage	X
AD2007-22-07	28.11.2007	Read AD	ECU upgrade	Read AD
AD2008-21-11	28.11.2008	Read AD	Uncontained release of engine debris	28.11.2016
AD2009-04-10	30.3.2009		Critical life-limited parts enhanced inspection	180d
AD2009-05-02	31.3.2009	Read AD	Engine fuel leaks	Read AD
AD2009-07-03	30.4.2009	Read AD	HPCR spool shaft stage 14 disk inspection	Read AD
AD2009-21-07	1.12.2009	MRAS ASB78A1162	Thrust reverser gearbox end actuator	500FC
<b>CF-700-2</b>				
AD1997-13-10	14.7.1997	(CF700) 72-154	Puhaltimen suojusten vaihtaminen.	010899
AD1997-25-08	25.2.1998	SBA72-155/-174	Osien vaihto	X
AD1998-23-06	30.11.1998		Polttokammion korjaus	010199
AD2001-10-12	18.6.2001		Osien vaihto	15072001
<b>CJ610-6</b>				
AD1997-25-08	25.2.1998	SBA72-155/-174	Osien vaihto	X
AD1998-23-06	30.11.1998		Polttokammion korjaus	010199
AD2001-10-12	18.6.2001		Osien vaihto	15072001
AD2010-09-08	28.5.2010	-	GE - replacement of AFT Technologies combu	Read AD
<b>CT7</b>				
AD1993-23-05	10.1.1994	SB A72-228	N/A	X
AD1993-25-17	2.2.1994	SB A72-252	N/A	X
AD1994-17-16	15.9.1994	SB A72-350R3	N/A	X

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
AD1996-26-01	10.3.1997	SB A72-381	CGT stage 2 cooling plate	X
AD1997-25-07	28.1.1998	SB A72-390/393R1	GGT disk failure	X
AD2002-01-03	12.2.2002		Stage 2 aft cooling plates	X
AD2003-08-52	15.4.2003	SB72-A0328R1	VG compressor rigging schedule	18042003
AD2004-07-09	11.5.2004	SB72-0452/0453	Inspection of PGB oil filter impeding bypass bu	(JP)
AD2007-08-01	14.5.2007	Read AD	Stage 2 turbine aft cooling plates	Read AD
SAD1-002	27.9.1984	SB72-27/28/31	Rework of compressor case	X
SAD1-003	20.11.1984	SB72-35	Modification of compressor rotor	X
<b>Honeywell International</b>				
<b>ALF502()</b>				
AD2006-09-13	13.6.2006	ALF502 72-0004	Drawdown schedule for 3rd stage turbine disc	X
<b>LF507-1F</b>				
AD2002-12-08	17.7.2002		GPT otor sealing plates	X
AD2002-22-06	18.11.2002	A72-1076R1	Combustion chamber liner inspection	(500CIS)
AD2009-26-06	11.2.2010	ALF/LF 73-1002	Cracks in fuel manifolds inspection	Read AD
<b>TFE731-5()</b>				
AD2010-06-11	21.4.2010	Read AD	Removing LPCR discs from service	100 CIS
<b>Pratt &amp; Whitney Aircraft Division of United Ai</b>				
<b>PW2040</b>				
AD1996-18-08	R1 10.11.1998		H&LP turbine	X
AD1997-11-51	R1 7.8.1997	PW2000-72-588	1st stage hp disk	X
AD1999-20-03	23.11.1999	PW2000-72-628	HPT disk fracture	X
AD2002-12-16	17.7.2002		Airworthiness limitations	X
AD2005-18-03	28.2.2006		Critical life-limited parts	31032006
AD2007-02-06	28.2.2007	PW2000 A72-706	Inspection of 8th stage drum rotor disks	X
AD2009-10-08	17.6.2009	PW2000-A72-734	HPT 2nd stage hubs	17.6.2009
AD2009-14-05	23.7.2009	PW2000 A72-736	Inspection of 12th stage disk in HPC drum roto	X
<b>Pratt &amp; Whitney Canada</b>				
<b>PT6T-()</b>				
CF-1987-14	R1 13.2.1989	SB5239	Ahtimen kuoren hitsisaumojen tarkastus	(600h)
<b>PW206()</b>				
CF-2004-06	31.3.2004	ASB A28252R2	Low cycle fatigue (LCF) count	X
CF-2004-06	18.7.2005	ASB A28252R2	DCU:n toiminta	AD
CF-2007-24	R1 10.1.2008	PW200-72-A28280	Turbine disk inspection and nut replacement	Read AD
<b>PW305()</b>				
CF-2007-25	R1 29.10.2007	Read AD	Engine HPC drum rotor cracks	500 h
CF-2008-08	R1 18.3.2008	ASB A24588R2	Engine fan blade fracture	30.9.2008
CF-2010-09	6.4.2010		Engine impeller in-service life reduction	6.5.2010
<b>PW545A</b>				
CF-2002-42	30.9.2002	SB30217R1	Inspection of flexible fuel tubes	28122002

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ	
<b>Rolls-Royce Corporation</b>					
<b>AE2100A</b>					
AD1999-03-09	1.3.1999	AE2100A-A-72-191	Reduced cyclic life limit of turbine wheels	X	
AD1999-17-09	7.9.1999	AE2100A-A-72-193	Propeller gearbox strut fitting	X	
AD2001-17-31	5.10.2001	A72-234R2/-153R2	HPT 2nd stage wheel	X	
<b>AE3007()</b>					
AD2000-11-22	21.6.2000		Moottorin tarkastus	M	
AD2000-13-01	20.7.2000	AE3007A-A-72-105	Turbiinipyörien käyntiaikarajoitus	M	
AD2001-17-31	5.10.2001	A72-234R2/-153R2	HPT 2nd stage wheel	X	
AD2001-19-03	29.10.2001		HPT turbine spacer	X	
AD2001-25-05	23.1.2002		Ahtimen akselin vaihto	X	
AD2003-25-08	21.1.2004		Turbine spacer life limits	X	
AD2004-04-05	9.3.2004	aE3007A-79-034	Bearing material contamination of the oil syste	(50H/5VRK)	
AD2007-24-05	2.1.2008	Read AD	Starter shaft seal modification	30.9.2009	
AD2009-08-51	10.4.2009	AE3007A-A-72-367	Inspection of HPT stage 2 wheels	X	
<b>Rolls-Royce Limited</b>					
<b>RB211-535E</b>					
CAA004-08-2000	R1	22.7.2003	RB.211-71-5291	Engine mount inspections	X
EASA2008-0176		2.10.2008	SB 72-AF996 R1	HP Turbine disc inspection	Remove dis
EASA2009-0244		23.11.2009	NMSB 72-AG272	LPT stage 1, 2 & 3 discs inspection	23.11.2009
G-2003-0007		18.9.2003	TLM05-20-01	Inspection of critical parts	05112003
G-2004-0027		22.11.2004	SB72-AE651	Inspection of the high pressure tubine	X
G-2005-0028	R1	30.9.2005	RB211-72-AE359	Inspection of high pressure compressor	JH
<b>Turboméca</b>					
<b>Arriel 1B</b>					
EASA2006-0068		4.4.2006	A292730251	Solenoidiventtiin asennuksen tarkistus	31072006
EASA2007-0002		8.1.2007	ASB292720231	Turbiinin johdesiipien tarkastus	31072007
EASA2007-0018	R1	27.8.2007	AD	Turbiinin siipien tarkastus ja turbiinin vaihto	AD
EASA2009-0002		8.1.2009	292 72 0276 verB	Alennusvaihteen välihammaspyörä	28.2.2011
EASA2009-0112	R1	21.7.2009	Read AD	Turbiinin siipien käyttöaika	1.7.2009
EASA2009-0236		12.11.2009	A292720810	Gas generator 2nd stage turbine	X
EASA2009-0245-E		12.11.2009	A292 72 0825 vB	Module 05 lubrication duct inspection	12.11.2009
EASA2010-0101	R2	7.4.2011	MSBA292 72 0831C	Post-TU347 second stage turbine disc - reduc	Read AD
EASA2010-0273	R1	2.3.2011	MSBA292720829B	Inspection of II stage turbine nozzle guide van	See AD
F-1990-064	R1	9.4.2001	SBA292-72-230	Kaasugeneraattorin puhdistus	SB
F-1995-069	R3	19.3.2001	292-72-0206/7/8	Moottorimuutoksia	15052001
F-2002-258		13.5.2002	SB292720258/65	Turbiininlapojen vaihto	31032003
<b>Arriel 1C2</b>					
EASA2009-0245-E		12.11.2009	A292 72 0825 vB	Module 05 lubrication duct inspection	12.11.2009
EASA2010-0101	R2	7.4.2011	MSBA292 72 0831C	Post-TU347 second stage turbine disc - reduc	Read AD

LKM	PVM	SB	OTSIKKO	TEHTÄVÄ
<b>Arriel 1D()</b>				
EASA2006-0068	4.4.2006	A292730251	Solenoidiventtiin asennuksen tarkistus	31072006
EASA2007-0002	8.1.2007	ASB292720231	Turbiinin johdesiipien tarkastus	31072007
EASA2007-0018	R1 27.8.2007	AD	Turbiinin siipien tarkastus ja turbiinin vaihto	AD
EASA2009-0002	8.1.2009	292 72 0276 verB	Alennusvaihteen välihammaspyörä	28.2.2011
EASA2009-0112	R1 21.7.2009	Read AD	Turbiinin siipien käyttöaika-rajaa	1.7.2009
EASA2009-0236	12.11.2009	A292720810	Gas generator 2nd stage turbine	X
EASA2009-0245-E	12.11.2009	A292 72 0825 vB	Module 05 lubrication duct inspection	12.11.2009
EASA2010-0101	R2 7.4.2011	MSBA292 72 0831C	Post-TU347 second stage turbine disc - reduc	Read AD
F-1990-064	R1 9.4.2001	SBA292-72-230	Kaasugeneraattorin puhdistus	SB
F-1995-069	R3 19.3.2001	292-72-0206/7/8	Moottorimuutoksia	15052001
F-2002-126	1.3.2002	SB292720261/0275	Ahtimen muutostyö	31052002
F-2002-258	13.5.2002	SB292720258/65	Turbiininlapojen vaihto	31032003
F-98-311	R1 20.10.1998	SB292720181/212	Kaasugeneraattorin tarkastus	SB
F-98-394	20.10.1998	SB292.72.0163R1	Kaasugeneraattorin takalaakeri	160199
<b>Arrius 2F</b>				
EASA2006-0237	14.9.2006	SB319734055	Polttoainesäätimen korjaus	31072007
EASA2007-0057	5.3.2007	SB319724012	Kaasunkehittimen etulaakerin vaihto	30042008
EASA2008-0170	8.10.2008	SB 319 79 4075	Voiteluyksikön muutostyö	31.5.2009
EASA2011-0182	6.10.2011	MSB 319 75 4810B	P3 air pipe - inspection/modification	Read AD
F-2005-073	28.4.2005	FAX057/05/DSO/TM	Moottorin korjaus	270402005
F-2005-088	14.6.2005	A319734823	Polttoaineensäätimen suodatin	31072005
F-2005-122	18.7.2005	ASB A319794802	Sulkuventtiin männän O-rengas	300H/500H
<b>Makila 1A()</b>				
EASA2006-0070	13.4.2006	SB298730241	Replacement of the LPG board of the ECU	31012007
EASA2007-0144	R1 1.6.2007	MSB298730250	Modification of engine control unit	30112008/2
EASA2009-0090	12.5.2009	Read AD	ECU hardware replacement	50h
EASA2011-0147	5.8.2011	MSB 298 77 0817	N2 sensor harness replacement	19.8.2011
F-1998-075	5.3.1998	A298.71.0137	Öljyn käyttö.	150398
F-2001-301	16.7.2001	ASL2102/01	Pakoputken tarkastus	(JP)
F-2001-524	13.11.2001	SB298730146/0166	Säätöyksikön korjaus	X
F-2002-124	1.3.2002	A298720148R1	Pakoputken muutostyö	30062003

**POTKURIT**

**Dowty Propellers**

[REDACTED]				
AD1993-19-01	20.10.1993	SF340-61-58	N/A	X
CAA003-05-99	1.5.1999	S2000-61-75	De-iced blade assembly	X
CAA004-09-97	1.9.1997	S2000-61-46	Back-up feather procedure	X
CAA004-11-94	1.11.1994	S2000-61-6	Propeller pitch control	X
CAA005-06-99	1.6.1999	S2000-61-26	New cylinder, piston and cover	X
CAA005-09-98	1.9.1998	S2000-61-67	Overspeed governorweights	X
CAA005-10-94	23.11.1964	SF340-61-82	Propeller hub cracks	X
CAA005-10-95	1.10.1995	S2000-61-22	Preload of cap screws	X
CAA005-12-94	1.12.1994	S2000-61-11	Blade retention bearings	X
CAA006-04-99	1.4.1999	S2000-61-73	Counterweight arm assy.	X
CAA006-08-97	1.8.1997	S2000-61-31	Pitch control unit servo valve	X
CAA006-09-95	1.9.1995	S2000-61-21	Governor overspeed weight carrier	X
CAA008-07-97	1.7.1997	S2000-61-47	Overspeed governor cap screws	X
EASA2009-0005	22.1.2009	Read AD	Hub assembly inspection	1200FH
SAD1-007	3.1.1990	SB61-A1021R10	Replacement of beta tube assemblies	X

**R.375/4-123-()**

EASA2008-0033	4.3.2008	SF340-61-A106	Blade outer sleeve inspection	Read AD
---------------	----------	---------------	-------------------------------	---------

**R381/6-123-()**

	17.10.2002	S2000-61-90	Propeller pitch control servo valve	X
--	------------	-------------	-------------------------------------	---

**Hamilton Sundstrand Corporation**

[REDACTED]				
AD2006-16-01	15.8.2006	14RF-19-61-113R1	Actuator yoke arm	15102006
AD2009-07-06	1.5.2009	ASB 568F-61-A47	Removing blades on 568F propellers	01062009
AD2011-04-02	16.3.2011		Removal from service of blades on 247F serie	15042011

**14SF-()**

AD1993-06-06	6.7.1993	ASB14RF-21-61-A3	N/A	X
AD1995-22-12	24.11.1995	ASB14SF-61-A59	PCU-servo	X
AD1996-01-01	19.1.1996	SB14SF-61-A95R1	Ultrasonic shear wave inspection	X
AD1996-08-02	9.5.1996	SB14SF-61-A95	Blade taper bore	X
AD1996-25-20	7.2.1997	SB14SF-61-70	Propeller control unit	X

<b>MOOTTORIN APULAITTEET JA JÄRJESTELMIEN LAITTEET</b>
--

AD1995-07-03	3.5.1995	GTCP85-49-A6831	Honeyweell International. APU exhaust center	X
AD1996-18-17	9.12.1996	TSCP700-49-A716	Honeyweell International. APU HPT disk failur	X
AD1997-04-04	24.3.1997	GTCP85-49-A7189	Honeyweell International. APU containment a	X
AD1997-19-18	27.10.1997	TSCP700-49-7266	Honeyweell International. LPC disk rim separat	X
AD2000-04-24	8.5.2000	GTCP36-49-7471	Honeyweell International. Uncontained APU fai	X
AD2004-24-03	3.1.2005	ASB-4503067-49-9	Hamilton Sundstrand Power System. Fuel filter	03072005
AD2005-23-11	14.12.2005	Katso AD	Hamilton Sundstrand. APU Compressor impell	X
EASA2007-0294	13.12.2007	SB 327-49-11	MICROTURBO. APU turbine wheel life limit re	13.12.2007
EASA2009-0100	18.5.2009	SB49-11A76R1	MICROTURBO. APU exhaust thermal insluatio	10/50FH
EASA2010-0079	10.5.2010		Microturbo - APU turbine wheel life limit reducti	Read AD

**RADIO- JA SÄHKÖVARUSTEET, LAITTEET JA AKUT**

AD1995-01-01		6.2.1995	SB-104	Terra Corporation. Replacement of xponder	X
AD1995-26-15	R1	26.12.1996	TPA-81A-34-82/84	Allied Signal TCAS FM revision	X
AD1999-23-22	R1	29.11.1999		Mode C transponder altitude reporting	28022000
AD2002-22-13		20.12.2002		Rockwell Collins. Flight management compute	20122004
AD2006-19-04		17.10.2006		Honeywell. Transponder erroneously going to	X
AD2009-08-01		14.5.2009	See AD	Upgrade of Honeywell IC-800 software	14052010
EASA2006-0265		13.9.2006		Check of Mode S and C transponders with Gilh	X
EASA2006-0269		14.9.2006	SWB MST67A-SW2	Honeywell Mode S transponder modification	29092006
EASA2006-0334	R1	14.11.2006	Read AD	Thales communications VHF data radio modifi	14.5.2010
EASA2007-0156		14.6.2007	A21-3851-002 etc	Honeywell. Transponder modification	x
EASA2008-0159		8.9.2008	Read AD	Honeywell. Mode-S transponder modification	8.9.2008
EASA2010-0003		19.1.2010	TDR-94()SIL07-2	Mode S transponder aircraft type mode strappi	19.4.2010
EASA2010-0067		26.4.2010	TDR-94( )	Rockwell Collins Inc. Mode S transponder che	Read AD
EASA2010-0204		20.10.2010	-94()-34-508/9	Rockwell-Collins. TDR-94 & TDR-94D Mode S	20102011
EASA2011-0043		30.3.2011	Read AD	Gables Engineering. Mod. Of Mode-S Transpo	30032013
EASA2011-0103		3.6.2011	SB 02/2011	Chelton Limited. ELT antenna modification/repl	Read AD
F-1999-472		22.12.1999		OMEGA-lennonsuunnistuslaitteiden poisto käy	01012000
F-2004-053		14.4.2004	457400-34-082..5	Thales Avionics. TA/RA VSI-TCAS indicator	31122007

**Honeywell International**

AD2010-07-02		3.5.2010	Read AD	Honeywell. Inspection of Primus II NV-850 NR	Read AD
AD2010-09-04		14.5.2010	Read AD	Honeywell Primus EPIC and Primus APEX - A	28.5.2010

<b>PELASTUSVÄLINEET</b>
-------------------------

AD1998-24-27		29.1.1999	SB26-110	FTFS fire extinguisher failure	X
AD1999-08-21		2.6.1999	C351-2000-35-1R2	Puritan-Bennett oxygen mask face cushion	X
AD2001-22-14		10.12.2001	OAS SB22-09-97	OAS. Fire extinguisher cartridge	05062002
AD2007-23-01		11.12.2007	SB 25-355	Goodrich. Pressure relief valve of the evacuati	17.7.2009
AD2008-06-27		28.4.2008	SB25-343R3/344R2	Goodrich. Modification of evacuation system	28042011
AD2009-21-10	R1	4.2.2010	Read AD	Avox systems. Oxygen cylinder rupture	17.3.2010
EASA2006-0286	R1	25.9.2006	GLD/GLF-35-150	Removal/emptying of oxygen reserve cylinders	X
EASA2009-0251-E		26.11.2009	Read AD	Fire Fighting Enterprises Ltd. Halonisammutti	28.11.2009
EASA2009-0262	R1	29.1.2010	ASB 26-115 iss C	Fire Fighting Enterprises Ltd. Halonisammutti	29.12.2009
EASA2009-0278		23.12.2009	Read AD	SICLI. Halonisammuttimet	4.2.2010
EASA2010-0062	R1	31.5.2010	FFE ASB 26-116 B	Fire Fighting Enterprises. Halon 1211 fire extin	14.8.2010
EASA2010-0152		9.8.2010	Read AD	Intertechnique, Eros - Oxygen mask regulator	9.2.2011
EASA2011-0090	R1	27.7.2011	MXH-350-240R2	Intertechnique Aircraft Systems. Oxygen mask	01062013
EASA2011-0094		6.6.2011	Aeraz.SB25-65-24	Aerazur. Life jacket vacuum bag modification	06122011
F-1992-246		25.11.1992	BS346.60.001	Aerazur life rafts	X
F-1996-112		5.6.1996	BS606.60.001	Aerazur life raft	X
F-1998-301		29.7.1998		Draeger emergeny oxygen generators	X
F-2001-351		8.8.2001	Inn7250-25-002/3	Babies bassinets	31122002

<b>VARUSTEET JA TARVIKKEET</b>
--------------------------------

AD1993-14-12		2.9.1993	Essex001R1	PBE	X
AD2002-22-12		13.12.2002	SB73-2	Titeflex Corp. Inspection of hoses	13122006
AD2006-04-04		24.3.2006	MSIL8930-26-01	Meggitt Model 602 smoke detector "lock up"	X
AD2006-17-13		27.9.2006	3410-25MR477	Recaro. Seat belt detaching due to short attac	X
CAA002-11-2001		18.12.2001	SB25-20-2658	B/E Aerospace Skyluxe II PAX seats	18012002
D-2004-151	R1	5.8.2004	SB3410-25MR477R3	RECARO. Detachment of seat belt connection	05102004
D-2008-386		10.12.2008		Weber Aircraft. Withdrawal of coffee maker C	10122008
EASA2006-0264		13.9.2006	SB180/A84-01R1	Aviointeriors passenger seats	13032008
EASA2008-0080		13.5.2008	SB 94-25-013	Sicma aero seat passenger seat inspection	13.11.2008
EASA2008-0097		3.6.2008	SB 94-25-013	Sicma Aero Seat passenger seat inspection	13.11.2008
EASA2008-0135		16.7.2008	Read AD	Aviointeriors S.p.A. Passenger seat backrest r	Read AD
EASA2011-0098		1.8.2011		Koito Industries. Replacement of passenger se	01082013/A
F-1994-085	R2	13.7.1999	SB90-25-005R1	Sicma aero seats track fittings	X
F-1997-134		18.6.1997	SB95-25-003	Sicma aero seat leg collars	X
F-1998-176	R1	12.8.1998		Baby cradle	X
F-2000-042		26.1.2000	SB133-25-006	Sicma aero seat head rest locking point	X
F-2001-605		12.12.2001	SB90-25-012R3	Sicma aero seat backrest links	X
F-2001-613		12.12.2001	SB90-25-013R2	Sicma aero seat backrest link repl.	X
F-2002-471	R1	27.11.2002	SB91-25-045	Sicma aero seat. Modification of seat belts atta	(650H)/311
F-2002-504		2.10.2002	SB92-25-005	SICMA aero seat. Central spreaders modificati	31122005
F-2004-132		14.8.2004	A320-25A1299	LERMER GmbH water boilers	31122004